

<b>REFERENCE:</b>	<b>TSB:</b> 21-016-25 REV. A <b>GROUP:</b> 21 - Transmission and Transfer Case	<b>Date:</b>	May 17, 2025	<b>REVISION:</b>	21-016-25
<b>VEHICLES AFFECTED:</b>	<p><b>**2025 (DT) RAM 1500 Pickup</b>  <b>2023 - 2025 (WS) Wagoneer / Grand Wagoneer</b>  <b>2023 - 2025 (WL) Jeep Grand Cherokee / Grand Cherokee L</b>  <b>This bulletin applies to the following:</b></p> <ul style="list-style-type: none"> <li>DT vehicles built on or after June 29, 2023 (MDH 0629XX) and on or before September 24, 2024 (MDH 0924XX) equipped with a 3.0L I6 Hurricane SO Twin Turbo ESS (Sales Code EFH) and 8-Spd Auto 8HP75 Trans (Buy-US) (Sales Code DFR).</li> <li>WL vehicles built on or after August 11, 2023 (MDH 0811XX) and on or before September 26, 2024 (MDH 0926XX) equipped with a 3.6L V6 24V VVT Engine Upg I w/ESS (Sales Code ERC) and the 8-Spd Auto 850RE Trans (Make) (Sales Code DFT) or the 8-Spd Auto 8HP50 Trans (Buy) (Sales Code DFW).</li> <li>WS vehicles built on or after August 03, 2023 (MDH 0803XX) and on or before October 25, 2024 (MDH 1025XX) equipped with a 3.0L I6 Hurricane SO Twin Turbo ESS (Sales Code EFH) or a 3.0L I6 Hurricane HO Twin Turbo w/ ESS (Sales Code EFC) and an 8-Spd Auto 8HP75 Trans (Buy-US) (Sales Code DFR).**</li> </ul>			<p><b>MARKET APPLICABILITY:</b></p> <p><input checked="" type="checkbox"/> NA                      <input type="checkbox"/> MEA  <input type="checkbox"/> SA                         <input type="checkbox"/> IAP  <input type="checkbox"/> EE                         <input type="checkbox"/> CH</p>	
<b>CUSTOMER SYMPTOM:</b>	<p>Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):</p> <ul style="list-style-type: none"> <li>U0101 - Lost Communication With The Transmission Control Module (TCM).</li> <li>U0402 - Implausible Data Received From TCM.</li> <li>U0418 - Implausible Data Received From Brake System Control Module 1.</li> </ul> <p>Customers may also comment on the following:</p> <ul style="list-style-type: none"> <li>Vehicle will go in limp-in mode. After the vehicle enters limp-in mode and has been shifted into Park, the vehicle will not shift into a forward or reverse gear.</li> </ul>				
<b>CAUSE:</b>	CAN terminals inside the valve body corrode losing communication with the vehicle.				

This bulletin supersedes Technical Service Bulletin (TSB) 21-016-25, date of issue February 14, 2025, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include converting this TSB to an RSU, updating the Vehicles Affected, adding new LOPs, Spare Parts and notes, and Repair Procedure steps and notes. Updates not highlighted by asterisks include removal of mechanical tools from the Special Tools/Equipment table.

**\*\*This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-095, date of issue May 17, 2025.\*\***

**REPAIR SUMMARY:**

This bulletin involves replacing the transmission valve body assembly.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
21-95-01-90	Valve Body - Replace <b>**WS/DT**</b> (0 - Introduction)	2 - Transmission and Transfer Case	2.0 Hrs.
<b>**21-95-01-91</b>	Valve Body, - Replace <b>WL</b> (0 - Introduction)	2 - Transmission and Transfer Case	2.1 Hrs.**
Failure Code	ZY	Service Action	

**SPARE PARTS:**

Qty	Part No.	Description	Notes
<b>**1 (AR)</b>	68661447AA	Transmission Valve Body	DT - Sales Code DFR
1 (AR)	68611157AB	Transmission Valve Body	WL - Sales Code DFY
1 (AR)	68611159AB	Transmission Valve Body	WL - Sales Code DFW**
1 (AR)	68612242AB	Transmission Valve Body	<b>**WS - Sales Code DFR for vehicles built on or before 02/14/2024.**</b>
1 (AR)	68661447AA	Transmission Valve Body	WS - Sales Code DFR for vehicles built on or after to 02/15/2024.
2 (AR)	68649162AA	Clamp, Exhaust	<b>**Replace only as needed.**</b>
7 (AR)	68218925AB	Transmission Fluid	

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition above, perform the repair procedure.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

**REPAIR PROCEDURE:**

**NOTE: \*\*This is not a proactive repair. This Repair Procedure is to only be performed under this RSU if the vehicle exhibits the symptom/conditions listed in this document.\*\***

1. \*\*Replace the transmission valve body.
  - **850RE** - Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info >21 - Transmission and Transfer Case / Automatic - 8HP50/850RE / Valve Body/ Removal and Installation.
  - **8HP75** - Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info >21 - Transmission and Transfer Case / Automatic -8HP75 / Valve Body/ Removal and Installation.\*\*
2. Program the TCM. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info >08 - Electrical / 8E - Electronic Control Modules / Module, Transmission Control(TCM) / Module Programming.
3. Clear all DTCs that may have been set.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*