

<b>REFERENCE:</b>	<b>TSB:</b> 02-002-25 <b>GROUP:</b> 02 - Front Suspension	<b>Date:</b>	May 21, 2025	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	2019 - 2025 (WL) Jeep Grand Cherokee/Grand Cherokee L 2019 - 2025 (JL) Jeep Wrangler 2019 - 2025 (JT) Jeep Gladiator 2019 - 2025 (D2) RAM 3500 Pickup 2019 - 2025 (WS) Wagoneer / Grand Wagoneer 2019 - 2025 (DT) RAM 1500 Pickup 2019 - 2025 (RU) Chrysler Pacifica 2019 - 2025 (DP) RAM 4500/5500 Cab Chassis 2019 - 2025 (DS) RAM 1500 Pickup 2019 - 2025 (DD) RAM 3500 Cab Chassis 2019 - 2025 (DJ) RAM 2500 Pickup 2019 - 2025 (MP) Jeep Compass 2019 - 2025 (GA) Alfa Romeo Guilia 2021 - 2025 (VF) RAM Promaster 2021 - 2025 (WD) Dodge Durango 2023 - 2024 (GC) Alfa Romeo Tonale 2023 - 2025 (GG) Dodge Hornet 2019 - 2025 (GU) Alfa Romeo Stelvio 2019 - 2023 (LA) Dodge Challenger 2019 - 2023 (LD) Dodge Charger 2024 - 2025 (LB) Dodge Charger 2024 - 2025 (KM) Jeep Wagoneer S 2019 - 2022 (VM) RAM ProMaster City	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA	<input type="checkbox"/> SA	<input type="checkbox"/> IAP
		<input type="checkbox"/> EE	<input type="checkbox"/> CH		
<b>CUSTOMER SYMPTOM:</b>	Leaking, noisy, or weak shocks or struts.				
<b>CAUSE:</b>	Any shock or strut related service that may require replacement				

**DISCUSSION:**

This Information Only TSB is to communicate the criteria for shock and strut diagnosing and replacement. If it is determined that a shock or strut is defective and needs to be replaced, only replace the defective shock or strut as required.

**NOTE: Do not replace any other shocks or struts because one is defective.**

**It is recommended to perform the following before any shock or strut replacement:**

- Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 02 - Front Suspension / Front / Diagnosis and Testing **OR** 17 - Rear Suspension / Diagnosis and Testing.
- Each shock or strut should be diagnosed separately.

### **Explanation of why shocks/struts mist or appear wet:**

- The reasons why misting occurs is usually evaporation of shock fluid from the rod under heated conditions. The evaporated fluid condenses and forms a mist on the shock body and cover. This is normal because a certain amount of shock oil must stay on the rod to lubricate it. Excessive runs and drips are something different and it is likely caused by damage to the rod or sealing system. Misting is most likely to be noticed at higher mileages due to accumulation.
- Some misting accumulation is normal and does not degrade ride performance.

**NOTE: Do not replace components for normal oil evaporation (misting). Continue to monitor these components.**

After any shock/strut replacement, it is important to note the performance of a new shock or strut changes over time and normalizes after a breaking in period of approximately 160 km (100 mi). The difference in performance between the left hand and right-hand sides, if it is noticed, will be quickly balanced out during this break in period.

### **POLICY:**

#### Information Only

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*