

- ATTENTION:**
- GENERAL MANAGER
  - PARTS MANAGER
  - CLAIMS PERSONNEL
  - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.


© 2025 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2025MY Forester  
 2023-25MY Ascent  
 2023-25MY Legacy & Outback  
 2024-25MY WRX  
 2024-25MY Impreza & Crosstrek

**NUMBER:** 06-95-25  
**DATE:** 05/29/25

**SUBJECT:** DTC C1C40 (Brake ECU) / Reprogramming File Availability

### INTRODUCTION:

This bulletin announces the availability of new reprogramming files developed to address cases of DTC C1C40 being detected by the Electronic Brake Booster (EBB) in addition to Failure Detail Code 30A2 stored within the Freeze Frame Data (FFD). This new software contains enhanced logic providing a more accurate detection of DTC C1C40. If this condition is experienced on an applicable vehicle, refer to the procedures outlined in this bulletin.

### PRODUCTION CHANGE INFORMATION:

The reprogramming files have been incorporated into vehicle production as per the table below.

Applicable Vehicle	Starting VIN
Forester	SH496101
Impreza/Crosstrek	TBD
Ascent	TBD
Legacy	TBD
Outback	TBD
WRX	S8800634

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

*Continued...*


**PFC FILE INFORMATION:**

SSM5-R reprogramming procedure					
Model	MY	File description	Old Part number	Old CID	New CID
Forester	25	26400SL032_042.pfc	26400SL031 26400SL041	B320250101	B320250102
IMPREZA & CROSSTREK	24	26400FN005_015_04D.pfc	26400FN014 26400FN04C	B220240106	B220240107
	25	26400SL032_042.pfc	26400SL041	B320250101	B320250102
Legacy & Outback	23-25	26400AN102_26400AN112 _26400AN09C_26400AN12 D.pfc	26400AN09B 26400AN12C	B120230103	B120230104
Ascent	23-24	26400XC02C.pfc	26400XC02B	B520230101	B520230102
WRX	24-25	26400VC112_122.pfc	26400VC121	B420240101	B420240102

**SERVICE PROCEDURE / INFORMATION:**

**STEP 1:** Using the Subaru Select Monitor, confirm the fault condition is applicable to this bulletin by verifying DTC C1C40 is detected by the electronic brake booster and failure detail code 30A2 is stored within the FFD. If the Failure Detail Code differs from code 30A2, diagnose and repair the vehicle as per the applicable Service Manual.

Status	Code	Description/ Failure part	Time Stamp		Occurrence Date	FFD
Current	C1C40	BRAKE ECU	xxx	xxx	2024/10/1	



Failure Detail Code	30A2
---------------------	------

**STEP 2:** Reprogram the Electronic Brake Booster following the normal SSM5-R procedure. Detailed information regarding the SSM5-R reprogramming procedures can be found in TSB 14-28-21R.

**REMINDER:** Customer satisfaction and retention starts with performing quality repairs.

Subaru of America, Inc. (SOA) highly recommends utilizing either the Subaru Midtronics DCA-8000 Dynamic Diagnostic Charging System or the Subaru Midtronics GR8-1100 Diagnostic Battery Charger to the vehicle and utilizing the Power Supply Mode feature anytime a vehicle control module is being reprogrammed. Once the Midtronics charger is connected to the vehicle, if the battery is fully charged, it takes less than three (3) minutes to boot-up the charger, select the Power Supply Mode, and have the battery voltage stabilized and ready for reprogramming.

**NOTES:**

- For instructions on using the Power Supply Mode, reference the applicable User Manual for the Midtronics DCA-8000 Dynamic Diagnostic Charging System and the Midtronics GR8-1100 Diagnostic Battery Charger on STIS
- Confirm all electrical loads such as lights, audio, HVAC, seat heaters, and rear defroster are all switched OFF before setting up the charger for Power Supply Mode.
- Select the correct battery type (Enhanced Flooded, Flooded, Gel, AGM or AGM Spiral).

*Continued...*

- Input the CCA which matches the vehicle's battery. **NOTE:** OE and replacement batteries have different CCA ratings. Always confirm the battery's CCA rating before proceeding.
- If using a DCA-8000 Dynamic Diagnostic Charging System, set the power supply voltage to 13.5 Volts.
- DO NOT connect the DST-i or DST-010 until the Power Supply mode function has completed its battery test mode and the Charging Voltage has dropped to and shows a steady 13.5 Volts on the display.
- Once Power Supply Mode reaches a steady 13.5 Volts, connect the DST-i or DST-010 to the OBD connector and proceed with initiating the normal SSM5-R reprogramming process.
- Amperage will fluctuate based upon the vehicle's demand for power. **NOTE:** If the voltage rises beyond 14 Volts while programming is in process, the procedure will abort. This can indicate a need to test or charge the vehicle battery before any further attempt at programming is made.
- ALWAYS set the power supply voltage to 13.5 Volts when using Power Supply Mode. NEVER turn the ignition switch on when charging at voltages 15 Volts or higher.

**REMINDER:** If the DCA-8000 or GR8-1100 indicates the vehicle's battery must be charged, charge the battery fully before proceeding to reprogram the vehicle while using the Power Supply Mode.

**NOTE:** Control module failures resulting from battery discharge during reprogramming are not a matter for warranty. Should any DTCs reset after the reprogramming update is performed, diagnose per the procedure outlined in the applicable Service Manual.

#### WARRANTY / CLAIM INFORMATION:

Labor Description	Labor Operation	Labor Time	Fail Code
BRAKE BOOSTER & REPROGRAMMING	A567-086	0.6H	QCZ-48

**IMPORTANT:** Always note the original Calibration Identification number (CID) / ROMID the vehicle came in with on the repair order **before** reprogramming and, make sure to list the **NEW CID / ROMID** for any newly installed programming (as confirmed from the actual control module **AFTER** installation). The **NEW CID / ROMID MUST** also be noted on the repair order as this information is required for entry in the Miscellaneous Detail field during claim submission. These numbers can be read using SSM5-R.

**NOTE:** You can confirm if a later version is available by entering the CID listed in this bulletin into SSM5-R. If a newer CID is shown as available in SSM5-R, reprogram using that file.

#### IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.