

**TECHNICAL SERVICE BULLETIN****Various Driver Assistance Feature Warning Messages Displayed In The IPC, Various Invalid Data/Lost Communication DTCs Stored In Various Modules****25-2249**

06 June 2025

Model:

Ford 2023-2025 Escape	equipped with minor feature code: DBCAB
Lincoln 2023-2025 Corsair	equipped with minor feature code DBCBC

Markets: North American markets only**Issue:** Some of the vehicles listed in the Model statement above may exhibit at least one of the following conditions:

- Various driver assistance feature warning messages in the IPC:
 - "Blind Spot System Fault"
 - "Cross-Traffic System Fault"
 - "Front Camera Fault - Service Required"
 - "Pre-collision Assist Not Available"
- Various data or lost communication DTC stored in various modules
- FDRS scan tool can not establish connectivity with the IPMA during a self test.

This may be due to the software installed in the IPMA.**Action:** For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to recover the IPMA and reprogram the IPMA.**Warranty Status:** Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.**Labor Times**

Description	Operation No.	Time
2023-2025 Escape/Corsair: Identify Minor Feature Code, Perform IPMA Self Test, Follow The Service Procedure To Establish Connectivity With The IPMA (Do Not Use With Any Other Labor Operations)	252249A	1.7 Hrs.

Repair/Claim Coding

Causal Part:	14G647
Condition Code:	04

Service Procedure

1. Identify the type of driver assistance package installed in the vehicle.
 - (1). Access [PTS](#).
 - (2). Enter the [VIN](#) in the vehicle ID tab.
 - (3). Scroll down to the vehicle information section.
 - (4). Select the link for additional information.
 - (5). Locate the minor feature code of the driver assistance package installed on the vehicle.
2. Is the vehicle a 2023-2025 Escape equipped with a minor feature code DBCAB?
 - (1). Yes - proceed to Step 4.
 - (2). No - proceed to Step 3.
3. Is the vehicle a 2023-2025 Corsair equipped with a minor feature code DBCBC?
 - (1). Yes - proceed to Step 4.
 - (2). No - this article does not apply, perform normal diagnostics outside of this article. Refer to the [WSM](#), Section 419-07 Lane Keeping System > Diagnosis and Testing.
4. Perform an [IPMA](#) self-test using the [FDRS](#) scan tool and check if [FDRS](#) establish connectivity with the module. The [IPMA](#) will be displayed in gray or purple if the module is not communicating with the scan tool. Does the [FDRS](#) scan tool establish connectivity with the [IPMA](#)?
 - (1). Yes - download and run the "IPMA – Image Processing Module A (IPMA) Software update" application. Proceed to Step 6.
 - (2). No - download and run the "IPMA – Image Processing Module A (IPMA) Recovery" application. Proceed to Step 5.
5. Does the [FDRS](#) scan tool establish connectivity with the [IPMA](#) after running the "IPMA-Image Processing Module A (IPMA) Recovery" application?
 - (1). Yes - download and run the "IPMA - Image Processing Module A (IPMA) A Software Update" application. Proceed to Step 6.
 - (2). No - this article does not apply, perform normal diagnostics outside of this article. Refer to the [WSM](#), Section 419-07 Lane Keeping System > Diagnosis and Testing.
6. Using the [FDRS](#) scan tool, download and run the "IPMA – Image Processing Module A (IPMA) Alignment" application and follow all on-screen instructions carefully.
7. Clear [DTCs](#).

© 2025 Ford Motor Company
All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy

and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.