



TECHNICAL SERVICE BULLETIN

Incorrectly Illuminated MIL With DTCs P0420 And/Or P0430

25-2267

24 June 2025

Model:

| | |
|---|--------------|
| Ford 2022 F-650/F-750 | Engine: 7.3L |
| 2021 F-53 Motorhome Chassis, F-59 Commercial Stripped Chassis | |
| 2022 E-Series | |

Issue: Some of the vehicles listed in the Model statement above may exhibit an incorrectly illuminated MIL with DTCs P0420 and/or P0430 stored in the PCM. This may be due to the software in the PCM.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to reprogram the PCM.

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

| Description | Operation No. | Time |
|--|---------------|----------|
| 2022 F-650/F-750: Retrieve DTCs, Reprogram The PCM And Perform The Catalyst Drive Cycle Procedure (Do Not Use With Any Other Labor Operations) | 252267A | 0.8 Hrs. |
| 2021 F-53 Motorhome / F-59 Stripped Chassis, 2022 E-Series: Retrieve DTCs, Reprogram The PCM And Perform The Catalyst Drive Cycle Procedure (Do Not Use With Any Other Labor Operations) | 252267B | 0.7 Hrs. |

Repair/Claim Coding

| | |
|-----------------|---------|
| Causal Part: | RECALEM |
| Condition Code: | 04 |

Service Procedure

1. Reprogram the PCM using the latest software level of the IDS scan tool.
2. Perform the Catalyst Drive Cycle Procedure. Refer to WSM, Section 303-14 > Description and Operation > Electronic Engine Controls - System Operation and Component Description. Repeat the self-test.
3. If P0420 and/or P0430 return, refer to the WSM, Section 309-00 for normal diagnostics. Repair as necessary outside of this article.

NOTE: Advise the customer that this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.

described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.