

REFERENCE:	TSB: 21-011-25 REV. A GROUP: 21 - Transmission and Transfer Case	Date:	June 28, 2025	REVISION:	21-011-25
VEHICLES AFFECTED:	2025 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on and before **May 06, 2025 (MDH 0506XX)** equipped with a 3.6L V6 24V VVT eTorque Engine UPG 1 (Sales Code ERG) and an 8-Spd Auto 850RE Trans (Sales Code DFT).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: **This bulletin applies to the North America market.**	
CUSTOMER SYMPTOM:	The customer must describe one or more of the following: <ul style="list-style-type: none"> • **No perceptible change when drive mode is selected. • Harsh or unstable launches in slippery or off-road conditions. • Drive mode operating in incorrect drivetrain configurations.** • Bump or jerk felt during Engine Start/Stop (ESS) operation in normal and snow modes. • Bump during tip-in downshift while in Normal or Sport modes. • Transmission shifting concerns when vehicle has less than 1500 miles (2414 Km). • Driveability concerns and not holding correct gear during downgrade, snow mode and accelerator tip-out maneuvers. 				
CAUSE:	TCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 21-011-25, date of issue January 21, 2025, which should be removed from your files. All revisions are highlighted with **asterisks**** and include an updated build date, new market note, added Customer Symptoms and new LOP.**

REPAIR SUMMARY:

This bulletin involves reprogramming the TCM with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-05-SQ	Module, Transmission Control (TCM) - Reprogram (0 - Introduction)	2 - Automatic Transmission	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the TCM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.