



Service Information

Offboard Diagnostic Information System Service (ODIS Service) Number: AOS-25-28

Subject: 2025 Q5 GUBAAY Notification Blindspot Hotfix Instructions

Date: June 5, 2025

To All Dealer Partners,

- This hotfix is for the: **2025 Q5**
- Vehicle effected: 2025 Q5

During test plan, you will get the error below:

— Test step: Analysis

Action: Message
Analysis

The following systems have been successfully calibrated:

NR4:
Horizontal angle: -1° [-4° - 4°]
Vertical angle: -0.22° [-4° - 4°]
The calibration was successful.

NR2:
Horizontal angle: -1° [-4° - 4°]
Vertical angle: -0.51° [-4° - 4°]
The calibration was successful.

NR1:
Horizontal angle: -1° [-4° - 4°]
Vertical angle: 1.36° [-4° - 4°]
The calibration was successful.

MFKS:
Pitch angle: -0.62° [-2.5° - 2.5°]
Roll angle: -0.13° [-2° - 2°]
Yaw angle: -0.33° [-2° - 2°]
The calibration was successful.

LRBS:
Horizontal angle: 0.44° [-2° - 2°]
Vertical angle: 0.28° [-2.5° - 2.5°]
The calibration was successful.

MRRS:
Horizontal angle: -0.03° [-5° - 4°]
Vertical angle: 0.28° [-2° - 2°]
The calibration was successful.

The following systems were not successfully calibrated:

NR3:
Horizontal angle: -1° [-4° - 4°]
Vertical angle: -1° [-4° - 4°]
The calibration failed!

- Hotfix number: A_2.38.1_LockID_Reihenfolge_vor_ZDC
- ODIS software version needed for this hotfix: Audi brand version 2.38.1


Important:


We recommend installation of this hotfix on one diagnostic device ONLY. Hotfix must be removed immediately after performing the procedure.




Service Information

1.0 Download Hotfix

1. Open a **Web Browser** on the diagnostic device and log on to **AccessAudi.com**
2. Navigate to **Elsa2Go>Service References>Software/Hardware Updates**
3. Search for **AOS-25-28 LockID_Reihenfolge Hotfix Zip File**
4. Click the **AOS-25-28 LockID_Reihenfolge Hotfix Zip File**  and **save** it to your Windows desktop.
5. Close your browser.
6. Browse to the desktop and double-click the **AOS-25-28 LockID_Reihenfolge Hotfix Zip File** to open it.
7. Right click the file (example only) name and select **Copy**:



8. Right click anywhere on the Windows desktop and select **Paste**. This file icon (example) must appear on the desktop:




(continued)




Service Information

2.0 – Install Hotfix into ODIS Service

1. Open ODIS Service (“Run as Administrator”)
2. Expand the **Data** submenu and click **Download** (under **Hotfix**):




3. Click **Continue**:






Service Information

- The Directory selection window will appear. Browse to and **highlight the Hotfix file** (*example only*), then click **Select Folder**:



- Click **OK**:



- Perform the diagnostic procedure.

Important:


The Hotfix must be removed after performing the procedure. Failure to do so will cause other vehicle diagnostics sessions to malfunction.




Service Information

3.0 – Uninstall the Hotfix from ODIS Service

1. Select **Erase** (under Hotfix), then **Continue**:



2. Click **OK** and close ODIS Service:



(continued)



Service Information

For questions or concerns for this **particular** hotfix, please reach out to Justin Warner,
248-754-4258

Product Support Engineer

VWGoA, Inc.

Product Quality & Technical Service