

# Technical Service Bulletin

<b>Topic</b>	EPB Warning light in DIP - Front door/s power latch system intermittent - DTC U112300 within Address 03 and Address 46
<b>Market area</b>	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2075034/3
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Jul 18, 2025

## Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0003 - Brake electronics	U112300: Data bus error value received		static
0046 - Convenience system central module	U112300: Data bus error value received		static
0046 - Convenience system central module	U112300: Data bus error value received		Intermittent
0003 - Brake electronics	U112300: Data bus error value received		Intermittent

## New customer code

Object of complaint	Complaint type	Position
assistance systems, comfort controls -> Parking Aid, Park Assist, Rear Traffic Alert -> reverse camera image	functionality -> too slow	
information, navigation, communication, entertainment -> TV operation -> display TV picture	functionality -> no function	
information, navigation, communication, entertainment -> navigation mode -> route guidance	functionality -> gives incorrect reading	
information, navigation, communication, entertainment -> navigation mode -> manage destination memory -> destination in destination memory	functionality -> deletes autonomously	
assistance systems, comfort controls -> Parking Aid, Park Assist, Rear Traffic Alert -> reverse camera image	functionality -> faulty	

information, navigation, communication, entertainment -> TV operation -> display TV picture	functionality -> faulty	
information, navigation, communication, entertainment -> radio, navigation, MMI and drive device functions -> screen display	functionality -> gives incorrect reading	front
information, navigation, communication, entertainment -> TV operation -> automatic TV channel search	functionality -> no function	
information, navigation, communication, entertainment -> TV operation -> TV reception -> digital TV reception	functionality -> no function	
information, navigation, communication, entertainment -> radio, navigation, MMI and drive device functions -> screen display	functionality -> faulty	front
assistance systems, comfort controls -> Parking Aid, Park Assist, Rear Traffic Alert -> reverse camera image	functionality -> too late	
information, navigation, communication, entertainment -> TV operation -> TV reception -> digital TV reception	functionality -> faulty	
assistance systems, comfort controls -> Parking Aid, Park Assist, Rear Traffic Alert -> area view camera image	functionality -> gives incorrect reading	
information, navigation, communication, entertainment -> radio, navigation, MMI and drive device functions -> switch device\MMI on\off -> start screen	functionality -> no function	
assistance systems, comfort controls -> Parking Aid, Park Assist, Rear Traffic Alert -> reverse camera image	functionality -> gives incorrect reading	
information, navigation, communication, entertainment -> TV operation -> TV channel tracking	functionality -> no function	

## Vehicle data

### Bentayga Series

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*
4V1*	2018	E		*	*	*
4V1*	2019	E		*	*	*
4V1*	2020	E		*	*	*
4V1*	2021	E		*	*	*
4V1*	2022	E		*	*	*
4V1*	2023	E		*	*	*
4V1*	2024	E		*	*	*
ZV1*	2023	E		*	*	*

ZV1*	2024	E		*	*	*
------	------	---	--	---	---	---

## Documents

Document name
master.xml

## Condition

One or a combination of the following is evident within the DIP (Figure 1)

- Electronic parking brake warning

And/or

- Drivers door power latch intermittent operation warning



Figure 1

- The front door/s power latching system sporadically does not work. The door remains in the first latch of the door lock but is not closed by the power latching system
- DTC U112300: Databus error value received Symptom 450560 evident within the ESP control unit (electronic stabilisation program) (J104)

And/or

DTC U112300 symptom code 65759 evident within the Onboard supply control unit 2 (J393)

## Technical Background

The micro switch signal of the door lock is not recognised or is recognised briefly, a counter press of the door by the operative is required to clearly recognise the signal

Insufficient back pressure of door (door closing loads / seal load) results in the pawl microswitch signal becoming too short. This short signal is then calculated as an error state by address 0003 -Brake electronics

### NOTICE

**NOTICE: Only adjust the required front door striker, you must only adjust both strikers if both sides are affected by the issue**

Before proceeding the operative must check to confirm if there are any other VIN applicable TPI's for this complaint within Elsa Pro

## Production Solution

Not applicable

## Service

### CAUTION

The following instructions **MUST** be conducted in the order shown. Warranty claims for latch replacement will be cancelled should with authorisation not have been given via a new or existing DISS query

1) Confirm the striker runs into the centre of the rotary latch of the door lock and adjust as necessary - Refer to Rep.Gr 57 - Door striker - To remove and fit

### NOTICE

In addition, adjust the striker as far as possible (at least 0.5 mm) further inwards (Figure 2)



Figure 2

If required adjust the door to the inside so that the front door is flush with the rear door - Refer to Rep.Gr 57. A small gap from front to rear door is possible and will not normally cause wind noises (Figure 3)




Figure 3

2) Check to confirm all door seals are correctly fitted and are fully engaged onto the vehicle body mounting points

- Check to confirm all door seals are in a serviceable condition

3) Check the function of the power latching system.

**!** NOTICE

**IMPORTANT: If the power latching system works correctly no further action is required at this point**

4) In individual cases it may be necessary to replace the outer door seal of the affected door

Refer to Rep.Gr 57 noting the following:

- Glue the new seal in the area of the door lock approximately 1 mm further inwards (Figure 4)





Figure 4

**Hint:** The power latching system should now permanently work correctly

However

Should the issue be evident the operative must respond via the open DISS query requesting further support and await feedback before conducting any further work

 <b>CAUTION</b>
<p>The following instructions <b>MUST</b> be conducted in the order shown. Warranty claims for latch replacement will be cancelled should with authorisation not have been given via a new or existing DISS query</p>

## Warranty

### Time to conduct procedure 1 - Time to adjust the front door striker (one door)

Warranty Type 110 or 910

Labour Operation Code 57 25 15 00

Damage Service Number 57 25

Damage Code 00 11

Time 20 Time units

### Time to adjust door striker (Both front doors)

Warranty Type 110 or 910

Labour Operation Code 57 25 16 00

Damage Service Number 57 25

Damage Code 00 11

Time 30 Time units

**Time to conduct procedure 2 - Replace x1 outer front door seal (when applicable)**

Warranty Type 110 or 910

Labour Operation Code 57 65 19 00

Damage Service Number 57 65

Damage Code 00 10

Time 90 Time units

**Required Parts and Tools**

If required: Outer door seal (self-adhesive) according to the ETKA parts catalogue