

# **Technical Information**

Service

**2025** ENU ASA6

4

# ASA6 - Check Air-Spring Strut on the Front Axle and Rework if Necessary (Stop Delivery/Recall Campaign)

Model Line: Taycan (Y1A/Y1B/Y1C)

Panamera (YAA/YAB)

Model Year: As of 2025 up to 2026

Concerns: Air-spring strut front axle

Cause: There is a possibility that the circlip on the front left and right air-spring strut on the affected vehicles was

not manufactured according to specifications.

If this is the case, the circlip on the upper side of the respective spring strut can loosen and air can thus

escape from the air-spring. As a result, it may cause an impairment of the driving characteristics, which

increases the risk of an accident.

Action: Check the air-spring strut on the left and right front axle and rework it depending on the test result.

Affected Only vehicles assigned to the campaign (see also PCSS Vehicle Information).


Vehicles:

### Service

ASA6 ENU **2025** 

# **Technical Information**

Installation Position:



Installation position of air-spring strut

#### Required tools

Tools: • Calliper gauge

#### Check air-spring strut on the front axle and rework if necessary.

Work procedure: 1 Remove (front) plenum panel cover − **only valid for Taycan**: ⇒ Workshop Manual '852219A3 Removing and installing (front) plenum panel cover'

Removing right and left plenum panel cover – **only valid for Panamera**:  $\Rightarrow$  Workshop Manual '852219A4 Removing and installing plenum panel cover'

2025

ENU ASA6

2 Measure the internal dimension of the circlip on the right and left air-spring strut using a calliper gauge. Proceed according to the default values specified below:


The internal dimension of the circlip on the **right** and **left** side of the vehicle is greater than or equal to 67.5 mm / 2.66 in:



End of action. Continue with Step 4.

Test result OK.

The distance between the ends of the circlips on the **right or left** side of the vehicle is **smaller than 67.5 mm / 2.66 in:** 



Test result not OK.


Continue with Step 3.


ENU **2025** ASA6

## **Technical Information**

Press circlip with pliers into the spring strut groove until the required internal dimension of at least 67.5 3 mm is reached.







Reworking circlip

Labor time: 25 TU

- Install plenum panel cover (front) only valid for Taycan: ⇒ Workshop Manual '852219A3 Removing and installing (front) plenum panel cover' Install cover for right and left plenum panel – only valid for Panamera: ⇒ Workshop Manual '852219A4 Removing and installing plenum panel cover'
- 5 Enter the campaign in the Warranty and Maintenance Logbook.

#### Warranty processing

Scope 1: Check front left and right air-spring strut – only valid for vehicles under Stop Delivery

#### Labor time:

Checking front left and right air-spring strut Includes: Removing and installing (front) plenum panel cover

⇒ Damage code ASA6 099 000 1

Jul 16, 2025 Page 4 of 5

## **Technical Information**

Service

**2025** ENU ASA6

4

Scope 2: Check and rework front left and right air-spring strut – only valid for vehicles under Stop Delivery

Labor time:

Checking and reworking front left and right air-spring strut Includes: Removing and installing (front) plenum panel cover

Labor time: 38 TU

⇒ Damage code ASA6 099 000 1

Scope 3: Check front left and right air-spring strut – only valid for vehicles under Recall

Labor time:

Checking front left and right air-spring strut
Includes: Removing and installing (front) plenum panel cover

Labor time: 41 TU

⇒ Damage code ASA6 099 000 1

Scope 4: Check and rework front left and right air-spring strut - only valid for vehicles under Recall

Labor time:

Checking and reworking front left and right air-spring strut Includes: Removing and installing (front) plenum panel cover

Labor time: 54 TU

⇒ Damage code ASA6 099 000 1

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.