

# V O L V O

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title <b>VCM Backup Battery Replacement</b>		Ref. No. <b>TJ 36916.2.0</b>	
Issuer (Dept.) <b>Technical Service</b>		Issue Date <b>6/25/25</b>	Status Date <b>7/1/25</b>
Car Market <b>United States and Canada</b>	Partner <b>3 US 7510 Volvo Car USA</b>	Function Group <b>3970</b>	
Function Description <b>Mobile data services</b>		Page <b>Page 1 of 2</b>	

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### DESCRIPTION:

If the vehicle is showing the DIM message 'Volvo on Call Service Required' and the DTC U105000 is set in the VCM, please follow advice under Service.

VCM = Vehicle Communication Module

BUB = Backup Battery in VCM

SP = Software Product

### CSC Customer Symptom Codes

Code	Description
JG	Volvo On Call/Other Volvo On Call problems

### DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
VCM	U105000	Permanent

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2022		-	201835-202221
225							2019-2022		-	201817-202221
227							2019-2022		-	201846-202221
234							2017-2021		-	201617-202121
235							2017-2021		-	201620-202121
236							2017-2021		-	201646-202121
238							2017-2021		-	201646-202121
246							2018-2021		-	201717-202121
256							2016-2022		-	201505-202221
536							2018-2024		-	201746-202414

## Technical Journal 36916.2.0

---

### SERVICE:

Replace the VCM Backup Battery and download the relevant SP, listed below.

SPA = 32398268

CMA = 32301733

\*You might get a pop up to say that this is not a valid SP. Just click YES, to continue.

### VST Operation Number

VST Operation Number	Description
39750-2	Vehicle Connectivity Module (VCM) remove-install/replace
39751-3	Back-up battery, (VCM) Replace

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3970.