

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: 08-002/25- FRONT PASSENGER SEAT BELT WARNING LIGHT FLASHES EVEN THOUGH THERE IS NO OCCUPANT IN FRONT PASSENGER SEAT (MEXICO ONLY)	Bulletin No.: 08-002/25
	Last Issued : 08/06/2025

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previous TSBs:	Date(s) Issued:
09-005/23	01/18/23
09-026/22	08/01/22

APPLICABLE MODEL(S)/VINS

Mexico Spec.:

2017-2025 MX-5 (Mexico spec. with standard seat and seat warmer - not with Recaro® seat)

DESCRIPTION

Some customers may complain that the front passenger seat belt warning light flashes and the seat belt warning beep is activated, even though there is no occupant in the front passenger seat. When a passenger seat occupant sits with a load on the front side for a long time with the seat warmer on, the occupancy sensor becomes dented and sensitive. As a result, the sensor determines that there is an occupant in the front passenger seat even though the seat is empty. Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Replace the passenger seat cushion pad with modified one according to the instructions on MGSS (SEAT CUSHION TRIM REMOVAL/INSTALLATION).
3. Verify the repair.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
NDY0-88-11X	Heater & Pad	1	Cloth and Leather

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's Safety Warranty for 5 years/60K miles.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9B
Part Number Main Cause	NDY0-88-11X
Quantity	1
Operation Number / Labor Hours:	XXW37DRX / 1.0 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.