

# McLaren 750S – Vehicle Software Platform 4.6 MY24, 5.3 MY25 and 6.0.1 MY26

<b>Bulletin type:</b>	Service Campaign
<b>Reference number:</b>	N/A
<b>Campaign reference:</b>	SCB 28 M 003
<b>Attention:</b>	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians
<b>Affected vehicles:</b>	McLaren 750S
<b>Situation:</b>	A new software platform has been released to update the McLaren 750S to the latest software 4.6 for MY24, 5.3 for MY25 and 6.0.1 for MY26.
<b>Procedure:</b>	Action affected vehicles on first opportunity (immediately if already on site or during next Retailer visit if not already on site). Please refer to the information outlined in this document to complete the required work
<b>Date:</b>	8 <sup>th</sup> August 2025

This bulletin will cover:

- 
1. Overview
  2. Procedure
  3. Re-Programming Procedure
  4. Warranty Information
  5. Affected Vehicles
- 

## 1. Overview

McLaren Automotive has released new software platforms to update the McLaren 750S MY24 to version 4.6, MY25 to version 5.2 and MY26 to version 6.0.1, for both Coupe and Spider variants. The software update will include improvements and bug fixes to improve the customer driving experience.

## 2. Procedure

To carry out the Service Campaign for Software Platforms 4.6, 5.3 and 6.0.1 update, software updates in multiple control units are required using McLaren Diagnostic System (MDS) 2.

Please refer to the next section which contains the relevant work instructions and care points.

## 3. Re-Programming Procedure

**Care Point:** When using MDS 2 to update the vehicle to the newest platform, **DO NOT** use MDS 2 version 1.23

For McLaren 750S MY24 Coupe, please follow the instructions and care points within the document '**Installation Instructions Platform Release 4.6 – McLaren 750S MY24**' attached with this Service Campaign Bulletin.

For McLaren 750S MY24 Spider, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 4.6 – McLaren 750S MY24 Spider**’ attached with this Service Campaign Bulletin.

For McLaren 750S MY25 Coupe, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 5.3 – McLaren 750S MY25**’ attached with this Service Campaign Bulletin.

For McLaren 750S MY25 Spider, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 5.3 – McLaren 750S MY25 Spider**’ attached with this Service Campaign Bulletin.

For McLaren 750S MY26 Coupe, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 6.0.1 – McLaren 750S MY25**’ attached with this Service Campaign Bulletin

For McLaren 750S MY26 Spider, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 6.0.1 – McLaren 750S MY25 Spider**’ attached with this Service Campaign Bulletin.

**Care Point:** Specific flashing order is required for successfully updating the vehicle software platform to 4.6 for MY24, 5.3 for MY25, and 6.0.1 for MY26. Always follow the correct control unit flashing order and instructions as specified in the installation instruction document and care points within

**Care Point:** Refer to Knowledge Article; KA-01191, ‘720S (P14) and 750S (P28) Current Software Platforms’

#### 4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
McLaren 750S – Vehicle Software Platform Update 4.6/5.3/6.0.1	0.75 hrs

**Care Point:** If previous software platform versions are required to be updated prior to carrying out the work on this Service Campaign, add the additional time to the Warranty Claim. Where additional time is required, the McLaren Warranty department will review and may request justification

#### 5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited (“McLaren”) are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.