

WNH2 – Re-Programming DME Control Unit (Workshop Campaign)

Important: **CRITICAL WARNING** - This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: **As of 2017 up to 2019**

Model Line: **718 Cayman (982) / 718 Boxster (982)**

Concerns: **DME control unit**

Cause: **Due to a software error in the DME control unit for the affected vehicles, the market-specific requirements of the OBD functions at an extreme altitude > 2,500 m above NHN are not completely met.**

Action: Re-program the DME control unit with the **latest** PIWIS Tester software release.
Minimum requirement: Release **42.250.050**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required tools

- Tools:**
- **P90999 - PIWIS Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g., **VAS 5908 90-A battery charger**

Re-programming DME control unit

- Work Procedure:** 1 The basic procedure for control unit programming is described in the Workshop Manual ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'* . .

For specific information on control unit programming during this campaign, see the table below.

Required PIWIS Tester software release:	42.250.050 (or higher)
Type of control unit programming:	Control unit programming using the ' Automatic programming ' function for the DME control unit: 'DME' control unit – ' Coding/programming ' menu – ' Automatic programming ' function.
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the DME control unit is re-programmed first, followed by the PDK control unit or transmission control unit, as the case may be . Both control units are then automatically re-coded . Do not interrupt programming and coding. Once the control units have been programmed and coded, you will be prompted to switch the ignition off and then back on again after a certain waiting time. Backup documentation of the new software versions is then performed.
The programming sequence takes (approx.):	12 minutes
Software release programmed during this campaign:	See ⇒ <i>Technical Information 'DME Software Overview'</i> section.
Procedure in the event of a termination in the control unit programming:	▪ Switch ignition off and then on again. ▪ Read out and delete the fault memory. ⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i> ▪ Repeat control unit programming by restarting programming.
Procedure if other error messages appear during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i> .

- 2 Read out and delete all control unit error memories.
 - 2.1 In the control unit selection ('Overview menu') press **F7** to call up the additional menu.
 - 2.2 Select the function "Read all error memories and delete if necessary" and press **F12** ('Next') to confirm.

- 3 End the diagnostic application. Switch off ignition. Disconnect Tester from vehicle.
- 4 Switch off and disconnect the battery charger.
- 5 Attach **Recall Proof of Completion label** to the front lid (**California dealers only**).

Instructions for attaching labels

- Surfaces on which you intend to attach the label must be clean, dry and free from grease and oil residues.
- Before attaching the label, clean the surfaces using a suitable cleaning agent and a clean, grease-free and lint-free cloth.
- This label must not be affixed over existing label.
- Attach label only at the specified positions.

- 5.1 Fill out the Recall Proof of Completion label
⇒ *Recall Proof of Completion Label* fully and correctly. This includes the recall code "WNH2", your dealer code and the repair date.

- 5.2 Clean the surface in the lower area on the front lid at the left-hand side in direction of travel at which the Recall Proof of Completion label must be attached ⇒ *Proof of Completion Label: specified position (Exemplary illustration — 718 (982) position accordingly)* -**arrow**- using a suitable cleaning agent and a clean, grease-free and lint-free cloth.

- 5.3 Affix Recall Proof of Completion label in the lower area of the front lid at the lefthand side in direction of travel ⇒ *Proof of Completion Label: specified position (Exemplary illustration — 718 (982) position accordingly)* -**arrow**-.

- 5.4 Close front lid.

- 6 Fill out **Recall Proof of Correction Certificate** and supply to customer (**California dealers only**). Proof of Correction Certificates can be ordered through PPL in packs of 250, or a template can be used which is found on PPN: <https://ppn.porsche.com/portal/docs/DOC-427025>
- 7 Enter the campaign in the Warranty and Maintenance booklet.

Recall Proof of Completion Label



Proof of Completion Label: specified position (Exemplary illustration — 718 (982) position accordingly)

DME Software Overview

718 Cayman
/ 718 Boxster
(982):

Type	Transmission variant	Model year	Software part number	Software release
718 Cayman / 718 Boxster	Porsche Doppelkupplung (PDK)	2017 – 2019	982906023CT	3753 (or higher)
718 Cayman / 718 Boxster	Manual transmission	2017 – 2019	982906023DA	3754 (or higher)
718 Cayman S / 718 Boxster S	Porsche Doppelkupplung (PDK)	2017 – 2019	982906024CT	3760 (or higher)
718 Cayman S / 718 Boxster S	Manual transmission	2017 – 2019	982906024DA	3761 (or higher)
718 Cayman GTS / 718 Boxster GTS	Porsche Doppelkupplung (PDK)	2018 – 2019	982906025AM	3767 (or higher)
718 Cayman GTS / 718 Boxster GTS	Manual transmission	2018 – 2019	982906025AN	3768 (or higher)

Warranty processing



Information

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary work and rework. The labor time may differ from the labor times published in the Labor Operation List in PCSS.

Scope 1:

Re-programming DME control unit

Labor time: Re-programming DME control unit Includes: Connecting and disconnecting battery charger Connecting and disconnecting PIWIS Tester Reading out and deleting fault memories Attach Recall Proof of Completion label and provide signed proof of correction to customer (California dealers only) Required parts:			Labor time: 39 TU
PNA EMI 000 00	Label – Recall Proof of Completion	1 ea.	
PNA 999 100 235	Certificate – Recall Proof of Correction	1 ea.	
* California dealers only: - For warranty processing, enter the Part No. PNA EMI 000 00 with the designation "label" as a local part at US\$ 0.34 in the warranty claim. - For warranty processing, enter the Part No. PNA 999 100 235 with the designation "certificate" as a local part at US\$ 0.01 in the warranty claim. ⇒ Damage Number WNH2 066 000 1			

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.