 <b>HYUNDAI</b> <b>Technical Service Bulletin</b>	GROUP <b>BODY ELECTRICAL</b>	NUMBER <b>25-BE-018H</b>
	DATE <b>SEPTEMBER 2025</b>	MODEL(S) <b>VENUE (QX)</b>
<b>SUBJECT:</b> INOPERATIVE HORN ASSEMBLY REPLACEMENT (WARRANTY EXTENSION TXXU)		

**This TSB supersedes 24-BE-018H to revise the Applicable Vehicles, Parts Information, Warranty Information, and Service Procedure sections.**

**Description:** Certain Venue (QX) vehicles may have an inoperable horn that may be caused by foreign substances causing internal parts to oxidize.

Hyundai is extending the warranty coverage for the horn replacement to 10 years or 120,000 miles from the date of original retail delivery or date of first use (whichever occurs first) and is valid for original and subsequent owners.

This bulletin provides instructions on the replacement of the inoperable horn.



Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.




**Applicable Vehicles:**

Model Year	Model	Production Dates
2020 – 2025	Venue (QX)	09/17/2019 – 08/30/2024

**Parts Information:**

Model	Part Name	Part Number	Figure	Remarks
Venue (QX)	Horn Kit	96629-K2100 QQH	 	Contents: 1. Horn Assembly - Low Pitch (QTY: 1) 2. Extension Cable (QTY: 1)

**Required Supplies:**

Model	Part Name	Part Number	Figure	Remarks
Venue (QX)	Black PVC Electrical Tape	N/A Source locally if necessary		Dealer will be reimbursed in sublet for use of tape.

**Warranty Information:**

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Venue (QX)	30D008R1	Horn Replacement & Extension Cable Installation	0.5 M/H	96611-K2000	B33	ZZ3

**NOTE 1:** If the affected parts are within the warranty period of 10 years or 120,000 miles, then submit as a campaign claim type. Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.

**NOTE 2:** Op times include VIN, Mileage, and repair justification photo(s) as outlined in the Digital Documentation Policy.

**NOTE 3:** The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

**NOTE 4:** If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

**NOTE 5:** Dealers will be reimbursed \$0.50 in sublet for use of tape under op code 30D008R1.

**Service Procedure:**

**DIGITAL DOCUMENTATION**



This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

**NOTICE**


Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

1. Turn **OFF** the ignition.
2. Disconnect the negative (-) battery terminal.

**Tightening Torque:**

lb-ft	6.5
lb-in	78
N.m	8.8

3. Refer to the shop manual to remove the front bumper assembly (A):
  - **Body (Interior and Exterior) > Front Bumper > Front Bumper Cover > Repair procedures**




4.


**DIGITAL  
DOCUMENTATION**

Using STUI, take a photo of the original horizontally mounted horn with the last 6 digits of the VIN and the date of repair on a piece of paper.


Upload the photo to STUI.



5. Refer to the shop manual to remove the horn (B) by disconnecting the horn connector and removing the mounting bolt:
- **Body Electrical System > Horn > Repair procedure**




6. Wrap the PVC Electrical Tape **10 mm** (~0.4 inches) (C) from the end of the female connector.



7. Install the new horn (D).

**i** Information


The supplied horn will be **VERTICALLY MOUNTED**.



8. Connect the extension wire to the horn's connector (E) and the front wiring harness connector (F).

**i** Information

Use the supplied extension cable to connect to the horn.



9. Reinstall parts in the reverse order of the removal process.
10. Verify the horn for normal operation.
11. This service procedure is now complete.