



Service Bulletin

Bulletin No.: PIP6068B

Date: September, 2025

PRELIMINARY INFORMATION

Subject:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2021-2025		All	All	6.2L L87	All
Cadillac	Escalade ESV	2021-2025		All	All	6.2L L87	All
Chevrolet	Silverado 1500	2022-2025		All	All	5.3L L84, 6.2L L87	All
Chevrolet	Suburban	2021-2025		All	All	5.3L L84, 6.2L L87	All
Chevrolet	Tahoe	2021-2025		All	All	5.3L L84, 6.2L L87	All
GMC	Sierra 1500	2022-2025		All	All	5.3L L84, 6.2L L87	All
GMC	Yukon	2021-2025		All	All	5.3L L84, 6.2L L87	All
GMC	Yukon XL	2021-2025		All	All	5.3L L84, 6.2L L87	All

Involved Region or Country	North America
Condition	As part of our ongoing quality improvement efforts, the E90 ECM part numbers 12711353, 12719704, 12731719 and 12740717 have been placed on restriction through TAC.
Cause	This restriction is intended to assist GM Engineering with product feedback.

Correction

Prior to contacting GM Technical Assistance for part authorization, verify the concern is not associated with the following:

Vehicles with DTCs P062B and/or P060C set in the ECM.

Note: If addressing DTC P060C, please review and follow the latest version of bulletin 25-NA-232 if applicable before proceeding.

If either or both of the DTCs are set perform the following:

Step 1: Verify ECM has the latest software, reprogram and re-evaluate as needed.

Step 2: Clear all DTCs, perform a global reset and re-evaluate.

Step 3: If either/both DTCs do not reset promptly after the previous step, do not attempt to replace ECM as this will not resolve this issue. (Additional information for 2023-2025 Model Years available in latest version of PIT6110) If either of the DTCs do reset promptly after the previous step than an ECM should be ordered.

If the vehicle is a 2023-2024 Silverado or Sierra equipped with 6.2L L87 engine and has a no start and/or no communication with the ECM condition after an Over the Air Update, please follow the latest version of PIP6083 prior to ordering an ECM.

If the previous concerns are not applicable, be sure to have the SI document that has led to ECM replacement available and be prepared to review diagnostic steps leading to ECM replacement with the TAC agent.

U.S. Dealers:

Please contact GM Technical assistance (TAC) by opening a case via Dealer Case Management (DCM) From the DCM home page in Global Connect, click on "New TAC Case" found on the Technical Assistance tab.

Canadian Dealers:

Call 1-800-263-7740 for English or 1-800-263-7960 for French.

Version	3
Modified	06/12/2025 Created on. 08/15/2025 to update correction information 09/08/2025 to update correction information

