



SIB 11 05 25

2025-09-17

DELIVERY STOP: S68T ENGINE - REPLACE UPPER OIL PAN SCREWS

This Service Information Bulletin (Revision 3) replaces SI B11 05 25 [AM1] [MM2] dated August 2025.

What’s New:

- Parts Information updated for F95, F96 and G07

☐	THIS REPAIR IS MOBILE FRIENDLY
☐	THIS REPAIR IS REMOTE SOFTWARE UPGRADE (RSU) FRIENDLY

MODEL

E-Series	Model Description	Production Date
F95	X5 M Sports Activity Vehicle	June 3, 2025
F96	X6 M Sports Activity Coupe	June 29, 2025
G07	X7 Sports Activity Vehicle	May 22, 2025 – May 23, 2025
G70	7 Series Sedan	April 14, 2025 – May 20, 2025
G90	M5 Sedan	April 16, 2025 – May 5, 2025

AFFECTED VEHICLES

- Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.
- Please make sure you check your dealer inventory as soon as possible. As of July 12, 2025, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG has issued a Delivery Stop (effective July 11, 2025) on certain Model Year 2025 - 2026 BMW vehicles that were produced between April 14, 2025, and June 3, 2025.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

Due to an assembly error the upper oil pan screws may not have been torqued correctly.

CORRECTION

Remove, replace and torque 6 of the of the upper oil pan screws.

PROCEDURE

1. Replace 6 specific upper oil pan screws with P/N 07 11 9 908 428 using Repair Instruction 11 13 020 “Remove and Install Lower Oil Pan Section”.

Do not remove the upper engine oil pan or the engine oil pump from the vehicle. Follow the supplemental instructions in the next step to replace each of the 6 affected screws one at a time after the lower oil pan is removed.

Only 6 screws are affected by this Delivery Stop.


2. Remove, replace and torque each screw **one at a time** using the sequence of numbers in the illustration below. Only replace the 6 screws highlighted in red.

Replace the 6 affected screws in positions 1, 3, 5, 6, 10 and 14 in that order only.

Torque the 6 new screws to the following:

Joining Torque: 10 Nm

Angle Torque: 90 degrees



PARTS INFORMATION

Use and invoice the applicable part numbers listed below.

F95 and F96 Vehicles Only:

Part Number	Description	Quantity
07 11 9 908 428	Hexagon bolt	6
12 61 7 604 790	Gasket	1
11 13 8 746 460	Sealing ring	1

07 11 9 963 300	Sealing ring	1
11 13 9 845 701	Oil sump with seal	1

For G07 Vehicles Only:

Part Number	Description	Quantity
07 11 9 908 428	Hexagon bolt	6
07 14 6 886 617	Multi-purpose bolt ASA	12
12 61 7 604 790	Gasket	1
11 13 8 746 460	Sealing ring	1
11 42 5 A34 A34	Oil filter cap with drain plug	1
07 11 9 963 300	Sealing ring (rounds to 10)	1
11 13 9 845 701	Oil sump with seal	1

For G70 Vehicles Only

Part Number	Description	Quantity
07 11 9 908 428	Hexagon bolt	6
07 14 8 869 310	Torx screw, self-locking	2
26 10 7 882 970	Hexagon bolt	3
26 12 7 536 563	Self-locking hexagon nut	1
07 14 7 301 867	Torx screw with washer	4
12 61 7 604 790	Gasket	1
11 13 8 746 460	Sealing ring	1
11 42 5 A34 A34	Oil filter cap with drain plug	1
07 11 9 963 300	Sealing ring	1
31 50 8 860 349	Repair kit oil seal on output	3
31 53 8 844 384	Assembly ring	1
31 51 1 213 527	O-ring	2
33 30 6 760 585	Combination nut	8
07 11 9 908 592	Hexagon screw with washer	4
31 20 6 866 022	Shouldered bolt with compression spring	2
07 11 9 906 100	Hexagon head collar bolt	2
31 10 6 866 023	Nut clip	2
34 10 8 838 589	Torx screw with washer	4
33 11 7 525 064	Screw plug with O-ring	2
32 30 6 778 609	Torx bolt	1
18 30 7 843 213	Sealing ring	2
18 30 9 504 710	Gasket	2
07 11 9 906 447	Countersunk head screw	4
18 30 7 597 650	Collar nut	4
07 11 9 906 089	Collar nut	2
18 30 9 909 376	Hexagon bolt	2
31 10 6 866 494	Torx screw with washer	1

07 14 7 283 812	Speed nut	2
07 14 6 875 114	Hexagon collar nut	4
33 30 6 787 062	Combination nut	2
51 61 8 084 883	Hexagon bolt	2
07 11 9 907 857	Hexagon screw with washer	2
51 71 6 966 566	Countersunk head screw with washer	4
07 11 9 904 124	Hexagon bolt	1
07 14 8 837 399	ASA bolt	4
11 13 9 845 701	Oil sump with seal	1

For G90 and F96 Vehicles Only

Part Number	Description	Quantity
07 11 9 908 428	Hexagon bolt	6
07 14 8 869 310	Torx screw, self-locking	2
26 10 7 882 970	Hexagon bolt	3
26 12 7 536 563	Self-locking hexagon nut	1
07 14 7 301 867	Torx screw with washer	4
12 61 7 604 790	Gasket	1
11 13 8 746 460	Sealing ring	1
11 42 5 A34 A34	Oil filter cap with drain plug	1
07 11 9 963 300	Sealing ring	1
31 50 8 860 349	Repair kit oil seal on output	3
31 53 8 844 384	Assembly ring	1
31 51 1 213 527	O-ring	2
33 30 6 760 585	Combination nut	8
07 11 9 908 592	Hexagon screw with washer	4
31 20 6 795 249	Shouldered bolt with compression spring	2
07 11 9 906 100	Hexagon head collar bolt	2
31 10 6 866 023	Nut clip	2
33 11 7 525 064	Screw plug with O-ring	2
32 30 6 778 609	Torx bolt	1
18 30 7 843 213	Sealing ring	2
18 30 9 504 710	Gasket	2
07 11 9 906 447	Countersunk head screw	4
18 30 7 597 650	Collar nut	4
07 11 9 906 089	Collar nut	2
18 30 9 909 376	Hexagon bolt	2
31 10 6 866 494	Torx screw with washer	1
31 10 6 866 496	Torx screw with washer	1
07 14 7 283 812	Speed nut	2
07 14 6 875 114	Hexagon collar nut	4
33 30 6 787 062	Combination nut	2
51 71 6 966 566	Countersunk head screw with washer	4

Copyright ©2025 BMW of North America, Inc.

07 11 9 904 124	Hexagon bolt	1
31 11 6 899 302	Multi-purpose bolt	12
07 14 8 837 399	ASA bolt	4
11 13 9 845 701	Oil sump with seal	1

Sublet – Bulk Supply Materials (RC 0011970700 without changing the engine oil filter)

Part Number	Description	Quantity
See SI B11 01 21	0W-30 LL01FE (Liters/One-tenth Liters)	10.3/103

Or

Part number used in conjunction with and for BMW Maintenance Program engine oil and filter service.

Part Number	Description	Quantity
See SI B11 01 21	0W-30 LL01FE (Liters/One-tenth Liters)	10.8/108

Additionally, other materials and small parts that are not specified above, such as fluids, lubricants (qty used in sublet), one-time use screws, nuts, and seals, which must be replaced or installed (according to the ISTA repair instructions/ETK/AIR), are to be selected from the Electronic Parts Catalog, and/or other approved BMW Group's resources according to the respective vehicle type. Invoiced these items separately under the Repair Code listed in this bulletin.

CLAIM INFORMATION

Reimbursement for this Action will be via normal claim entry utilizing the applicable work package information below and the part numbers listed above that apply.

Repair Code:	0011970700	F95 F96 G07 G70 G9x S68T Reworking threaded connection, upper oil sump section
---------------------	-------------------	---

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer (New in-stock/No in-service date), or the vehicle is already in the workshop for another reason and/or repair.

Work Pkg	Labor Operation	Description (Plusposition)	Labor Allowance
# 1	00 78 766	Renew the 6 hexalobular screws (M6x25) on the upper oil sump section (without resetting the CBS data)	18 FRU (F95, F96); 19 FRU (G07); 43 FRU (G70); 63 FRU (G90); 64 FRU (G99)
Or:			
# 2	00 78 767	Vehicle was already taken care of through another repair or Technical Campaign	1 FRU

Or:

The vehicle arrives at your center and this Action shows open (No other Main work will be performed or claimed during this workshop visit).

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 78 219	Renew the 6 hexalobular screws (M6x25) on the upper oil sump section without resetting the CBS data)	19 FRU (F95, F96); 21 FRU (G07); 45 FRU (G70); 65 FRU (G90); 65 FRU (G99)
Or:			
# 4	00 78 767	Vehicle was already taken care of through another repair or Technical Campaign	1 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Reference the SIB number, the issue (briefly), and the work package (WP) number performed in the technician's RO notes, and in the claim comments (For example: B11 05 25 Replace upper oil pan hexalobular screws WP 1), unless otherwise required by State law.

And:

Sublet – Bulk Supply Materials (RO and Claim Comments Required)

Sublet Code 4	Reimbursement for the supported repair-related bulk supply materials amount (Do not use the BMW part numbers for claim submission)	Up to 220.00
----------------------	--	--------------

Sublet reimbursement calculation for claiming the applicable repair-related bulk supply materials (BMW part numbers) is at the dealer net (DN) price for the full or proportional quantities used plus your center's handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

BMW Maintenance Program

If the vehicle has an active maintenance program and the Engine oil Service task shows Recommended, Due in the Service status field, or if it is Bundling Eligible (BE), change the engine oil and filter after replacing the engine oil pan's upper screws.

Claim and submit for the Work Package # 1 RO line item.

Repair Code: 0011970700 - Work Package # 1

Labor Operation	Description (Plusposition)	Labor Allowance
00 78 766	Renew the 6 hexalobular screws (M6x25) on the upper oil sump section (without resetting the CBS data) (Includes replacing the Oil filter cap)	See above

Then, as additional RO line item for and under the BMW Maintenance Program:

- Claim and submit for the Standard scope labor operation code 00 00 105 (Main work)

Labor Operation	Description	Labor Allowance
00 00 105	Standard scope of service (Main work)	2 FRU

And:

- **Repair Code: Applicable BMW Maintenance Program Oil Service Task (First, or all after the First).**
- Claim and submit for the engine oil (10.8 liters), and oil filter part number under the BMW Maintenance Program Engine “oil service task” Repair Code that applies

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Service Action’s repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Repair Code noted above as follows:

- Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to [SI B01 29 16](#) for additional information.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

