

<b>REFERENCE:</b>	<b>TSB:</b> 18-032-25 REV. A <b>GROUP:</b> 18 - Vehicle Performance	<b>Date:</b>	September 17, 2025	<b>REVISION:</b>	18-032-25
<b>VEHICLES AFFECTED:</b>	<b>2025 (DT) RAM 1500 Pickup</b> This bulletin applies to vehicles <b>**built on or after August 11, 2023 (MDH 0811XX) and on or before April 24, 2025 (MDH 0424XX)**</b> equipped with the 3.0L I6 Hurricane HO Twin Turbo ESS (Sales Code EFC).			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input checked="" type="checkbox"/> CH <b>NOTE:</b> This bulletin applies to the North and South America, Enlarged Europe, Middle East & Africa, India & Asia Pacific and China markets.	
<b>CUSTOMER SYMPTOM:</b>	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set the following Diagnostic Trouble Code (DTC): <ul style="list-style-type: none"> <li>• P018B-00 - Fuel Pressure Sensor "B" Circuit Range/Performance.</li> </ul> Customers may experience <b>**one or more of **</b> the following: <ul style="list-style-type: none"> <li>• <b>**Vehicle speed limited to 98 MPH (157.7 KPH). **</b></li> <li>• A potential to stall when coming to a stop with an immediate restart. If the engine were to stall while stopping, a message would display in the cluster informing the driver to shift to park to restart the engine.</li> </ul>				
<b>CAUSE:</b>	PCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 18-032-25, date of issue June 19, 2025, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include an updated/new vehicle build dates, Customer Symptom, converting to an RSU, new note, new Repair Summary statement, new Claims Data table, new Diagnosis statement and new Repair Procedure steps.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-197, date of issue September, 17 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

**NOTE: \*\*The RSU portion of this service bulletin covers the North America markets.\*\***

**REPAIR SUMMARY:**

**\*\*This bulletin involves Inspecting and possibly reprogramming the PCM with the latest available software.\*\***

**\*\*CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-06-9F	Module, Powertrain Control (PCM) - Inspect (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.
18-19-06-9G	Module, Powertrain Control (PCM) - Inspect And Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.
Failure Code	RF	Required Flash	
	CC	Customer Concern	

**The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.**

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code “RF” (Required Flash) can no longer be used on Technical Service Bulletin flashes. The “RF” failure code must be used on an RSU.
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.\*\*

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTC)s or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

\*\*If a customers VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.\*\*

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. \*\*Is the vehicle on the RSU VIN list?

- YES>>> Proceed to [Step 2](#).
- NO>>> Proceed to [Step 3](#).

2. Is the PCM software updated to the latest version?
  - YES>>> This bulletin is complete. Use Inspect LOP (18-19-06-9F) to close this active RSU.
  - NO>>> Proceed to [Step 3](#).\*\*
3. Reprogram the PCM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
4. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.**

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*