

95B.III – Macan Rear Lid Does Not Open/Close

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan	As of 2023 up to 2026	95B	N/A	N/A

Revision History

Revision	Release Date	Changes
0	September 24, 2025	Original document

Condition

The customer states the rear lid does not fully close when contacting the lower latching bar (also referred to as the striker plate, see Fig. 1, below). In these cases, the tailgate can remain slightly open or begin to reopen while emitting a warning sound even if there is no obstruction.

This condition results in the tailgate remaining slightly open, some customers report the lid getting stuck and the inability to reopen/close the rear lid remotely. These customers often force the trunk open or close it using manual force.

During these events the instrument cluster will display tailgate open with a solid tone until the lid is forced closed. The message is consistent while vehicle is on.

The BCM2 fault code Rear-end electronics: 803008 - Trunk lid closing aid motor, signal implausible may result.

Technical Background

The condition described above can occur if the placement of the locking bar in the 95B.III Macan is set too high causing contact too soon (See Figure 1).




Figure 1 - Rear locking bar (Circled)

Service Information

Adjust rear locking bar (the striker plate) down one 'index' level (Refer to Figure 2) and test to validate the repair successfully resolves the closing operation issue.



Figure 2 - Rear locking bar 'index' level adjustment

Warranty

For documentation and warranty invoicing, enter the working position and PCSS encryption specified below in the warranty claim:

APOS	Labor operation	I No.
03350050	On board diagnostic	
03350053	On board diagnostic-Create VAL	
55861950	Lower part of rear lid lock remove and reinstall	

PCSS encryption:

Location (FES5)	55860	Lower part of rear lid lock
Damage type (SA4)	1111	Adjustment fault

Search Items

Macan, Rear Lid, Striker Plate, Trunk Lid, 95B, MY24

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.