



Service Bulletin

Bulletin No.: PIC6602K

Date: October, 2025

PRELIMINARY INFORMATION

Subject: IOK Radio Issues

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
BrightDrop	Zevo 600	2023		All	All	All	All
Chevrolet	Corvette	2024-2025		All	All	All	All
Chevrolet	Silverado 1500	2022-2026		All	All	All	All
Chevrolet	Silverado 2500	2024-2026		All	All	All	All
Chevrolet	Silverado 3500	2024-2026		All	All	All	All
Chevrolet	Suburban	2022-2024		All	All	All	All
Chevrolet	Tahoe	2022-2024		All	All	All	All
GMC	Sierra 1500	2022-2026		All	All	All	All
GMC	Sierra 2500	2024-2026		All	All	All	All
GMC	Sierra 3500	2024-2026		All	All	All	All
GMC	Yukon	2022-2024		All	All	All	All
GMC	Yukon XL	2022-2024		All	All	All	All
GMC	Hummer	2022-2025		All	All	All	All

Involved Region or Country	United States
Additional Options (RPO)	IOK
Condition	<p>Customers may comment of:</p> <ul style="list-style-type: none"> No audio concerns. Blank, Black, Freezing/Frozen, or Glitching Display screen. "Return to Dealer" or "Demo Mode" message on the display.
Cause	Concerns may be software, connection, or hardware.

Correction

Note: If the VIN you need a radio for is part of [N252504460](#) - Customer Satisfaction Program - Radio Replacement and Reprogramming this PI is not applicable, please call/order as per step 1.4 below and state that the part is required for a VIN applicable to [N252504460](#) - Customer Satisfaction Program - Radio Replacement and Reprogramming

1. For a blank or black screen that cannot be viewed refer to PIC6540 and perform a reset on the radio to see if display returns, continue with steps below. If display does not return, follow normal SI diagnostics

1.1 For a return to dealer or Demo Mode message displayed on the radio screen see PIT6209.

1.2 Verify the radio software is up to date:

- 25-NA-121 for 2022-2025 LD trucks. 2024-2025 HD Trucks and 2022-2024 SUVs
- 24-NA-168 for Hummer 2022-2024
- 25-NA-098 for Corvette and MY2025 Hummer

If the radio is not at latest software level update the radio, clear all codes and recheck for concern.

1.3. If concerns continue disconnect, inspect, and reconnect all related connections, clear any codes and recheck for concern.

1.4. If concern is still present and a new radio is needed, these radios are currently restricted through the Electronic Service Center (ESC). Please contact your preferred ESC to order the new radio. The ESC will require a response to the attestation question before authorization will be provided. Attestation question: Have you followed , reset the module, installed the latest software, disconnect and reconnect, and that the radio still requires a replacement?

2. For audio concerns including intermittent 1-2 second loss of audio or loss of audio for an entire ignition cycle see PIT6406.

Note: If issue aligns with PIT6406 do NOT replace the radio for this issue as it will not correct it. Engineering is aware of the issue and investigating the root cause for each scenario for loss of audio please be patient until a resolution is published

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2810335	Update radio to latest software	Use Published Labor Time
*3480578	Disconnect and reconnect Radio module	1.0 Hrs.
*3480688	Radio Replacement per TAC Instructions	MY22-25 Hummer SUV and Pickup 1.1 Hrs. MY22.5-25 Silverado and Sierra 1500 1.2 Hrs. MY24-25 2500/3500HD 1 Hr. MY24-25 Corvette 1.3 Hrs. MY22-24 Tahoe/ Suburban/ Yukon/Yukon XL 1.1 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	11
Modified	04/30/2025 Created on.

05/01/2025 - Updated Correction.
05/13/2025 - Updated Correction.
05/29/2025 - Updated Models.
06/19/2025 - Update to the Correction.
06/30/2025 - Update to correction
07/23/2025 - Updated correction to ESC restriction
07/30/2025 - Update to correction
08/14/2025 - Updated to correction to ESC restriction
10/03/2025 - Updated to change labor operation for programming per BQM request
10/08/2025 - Updated to add note to not replace radio for audio issues

