

GENERAL MOTORS
DCS7364
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 3, 2025

Subject: N252508360 - Special Coverage
Turbocharger Replacement

Models: 2022 Chevrolet Malibu

General Motors is releasing Special Coverage N252508360 today.

What Should Dealers Do: Dealers can review the attached bulletin and it will also be displayed in Service Information tomorrow. This Special Coverage can be seen in the Applicable Warranties section in Investigate Vehicle History (IVH).

END OF MESSAGE

Special Coverage

N252508360 Turbocharger Replacement



Release Date: November 2025

Revision: 00

Attention: This Special Coverage can be seen in the Applicable Warranties section in Investigate Vehicle History (IVH).

Make	Model	Model Year	
		From	To
Chevrolet	Malibu	2022	2022

Involved vehicles are identified on the Applicable Warranties section in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain vehicles listed above may have a condition that could cause the turbocharger to fail. If this condition occurs, the Malfunction Indicator Lamp (Check Engine Light) will illuminate, and a diagnostic trouble code will set. Additionally, a message may be displayed indicating the vehicle's available engine power is reduced.
Special Coverage	<p>This special coverage covers the condition described above for a period of 15 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.</p> <p>For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after November 3, 2025, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to November 3, 2025, must be submitted to the Service Contract provider.</p> <p>Vehicle owners or lessees who paid for repairs referenced in this Special Coverage ("Customers") are eligible for reimbursement of their reasonable and customary expenses in accordance with the procedures specified below. The conditional right to reimbursement is provided by GM solely in the interest of customer satisfaction and is personal to Customers. <i>Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.</i></p>
Correction	Dealers are to replace the turbocharger as necessary. The repairs will be made at no charge to the customer.

Parts

Quantity	Part Name	Part No.
1	Turbocharger	25207489
2	Turbocharger Oil Feed Pipe Washer	12662184
1	Turbocharger Oil Return Pipe Gasket	12653753
1	Turbocharger Pipe Fitting	12685113
1	Turbocharger Oil Return Pipe Gasket	12640468
4	Turbocharger Nut	11612078
1	Turbocharger Heat Shield	12673929
1	Turbocharger Heat Shield	25204202
1	Turbocharger to Catalytic Converter Gasket	12641115
1	Exhaust System Front Gasket	23238284
1	Turbocharger Exhaust Pipe Clamp	12643268
5	Turbocharger Coolant and Oil Feed Pipe Seal	12662185
1	Turbocharger Oil Feed Pipe Seal	12662186
1	Turbocharger Coolant Feed Pipe Seal	12676405
1	Exhaust System Intermediate Gasket	22816982
1	Dexcool	12346290

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect. **Due to limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Special Coverage

N252508360 Turbocharger Replacement



Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9900954	Diagnostic Time Only – No Further Action Required	0.1-1.0	ZREG	N/A
For vehicles WITHIN the New Vehicle, Powertrain Ltd, CPO Powertrain Ltd, or Emission Ltd Warranty, utilize the regular warranty labor op. For vehicles OUTSIDE of the New Vehicle, Powertrain Ltd, CPO Powertrain Ltd, or Emission Ltd Warranty, utilize labor op 9900955	Turbocharger Replacement Add: Diagnostic Time	4.6 0.1-1.0	ZREG	N/A
9900956	Customer Reimbursement Approved - For USA and Canada dealers only - For Export dealers only	N/A 0.2	ZREG	*
9900957	Customer Reimbursement Denied – For USA dealers only	N/A	ZREG	**

Please Note: The above labor time(s) are published direct from the Labor Time Guide.

* For USA and Canada: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. Submit \$20.00 USD (\$25.00 CAD) administrative allowance in Net/Admin Allowance.

For Export: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement.

** Submit \$10.00 administrative allowance in Net/Admin Allowance.

Service Procedure

- A vehicle may come in with P0299 or other turbocharger-related DTCs. Following the troubleshooting chart in SI may lead to turbocharger replacement.
 - If the troubleshooting chart does NOT lead to turbocharger replacement, no further action is required. Inform the customer that any additional repairs will have to be handled under customer pay.
 - If the troubleshooting DOES lead to turbocharger replacement, proceed to step 2.
- Replace the turbocharger. Refer to *Compressor Air Intake Turbocharger Replacement* in SI.

Customer Notification

General Motors will notify Customers of this special coverage on their vehicle (see copy of sample Customer letter included with this bulletin).

Customer Reimbursement

Customer requests for reimbursement of previously paid repairs to correct the condition described in this bulletin are to be submitted to the dealer prior to or by November 30, 2026. See General Motors Service Policies and Procedures Manual (USA & Canada) or local Policies and Procedures, for details.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**

Special Coverage

N252508360 Turbocharger Replacement



This notice applies to your vehicle, **VIN:** _____

Dear General Motors Customer:

As the owner of a GM vehicle, your satisfaction with our product is very important to us.

This letter is intended to make you aware that some vehicles may have a condition that could cause the turbocharger to fail. If this condition occurs, the Malfunction Indicator Lamp (Check Engine Light) will illuminate, and a diagnostic trouble code will set. Additionally, a message may be displayed indicating the vehicle's available engine power is reduced.

Do not take your vehicle to your GM dealer as a result of this letter unless you believe that your vehicle has the condition as described above.

What We Have Done: General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your GM vehicle within 15 years of the date your vehicle was originally placed in service or 150,000 miles (240,000 km), whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program. For customer's vehicles already outside of the above years and/or miles, we are still offering reimbursement if the issue occurred within the years and miles stated above. Please follow the reimbursement steps below.

What You Should Do: If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage **must be performed by a General Motors dealer**. You may want to contact your GM dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

Reimbursement: If you already paid for repairs for the condition described in this letter, **and those repairs were completed prior to this mailing**, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by November 30, 2026, unless state law specifies a longer reimbursement period.

The right to submit reimbursement claims is provided by GM solely in the interest of customer satisfaction and is personal to vehicle owners and lessees who previously paid for repairs referenced in this Special Coverage ("Customers"). **Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.**

You may schedule your vehicle for repair using the QR code below. For more information about your vehicle, or if you have questions or concerns that your dealer is unable to resolve, please visit gm.com/service. You can also use your preferred voice assistant (for example, "Please go to GM.com"), or call the Buick, Chevrolet or GMC Customer Assistance Center at 1-866-467-9700. For Cadillac, please call 1-800-333-4223.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

We are sorry for any inconvenience you may experience; however, we have taken this action in the interest of your continued satisfaction with our products.

Neelie O'Connor
Global Executive Director
Customer Experience Operations

Scan here to
locate a dealer.

Special Coverage
N252508360 Turbocharger Replacement



Enclosure
N252508360