

**Various Error Messages Regarding Driver Assistance Systems in the Instrument Cluster in Conjunction With Passive Fault Memory Entries in the Distance Measuring Sensor Control Unit (ACC1) (84/25)**

Model Line: **911 (992)**  
**Taycan (Y1A/Y1B/Y1C)**  
**Panamera (YAA/YAB)**  
**Cayenne (9YA/9YB)**

Model Year: **As of 2018**

Equipment: **Depending on the model line and respective vehicle equipment, possible M-no.:**

- ACC High End with Innodrive (**I-No. 3V1**)
- ACC InnoDrive with speed limiter (**I No. 3V2**)
- ACC with speed limiter (FOD) (**I No. 3V9**)
- Automatic distance control (ACC) (**M-No. 8T3**)
- ACC with speed limiter (**M-no. 8T8**)

Concerns: **Distance measuring sensor control unit (ACC1)**

Cause: **The customer complains about the failure of various driver assistance systems and corresponding (white) messages in the instrument cluster, for example:**

- Assistance Systems currently reduced
- Lane Keep Assist currently not available
- Active Lane Keeping currently not available
- Speed limit display not available
- Proactive occupant protection currently reduced
- Warn and Brake Assist reduced
- Driving light control faulty
- Emergency Stop Function currently not available

After an ignition cycle, all systems are available again and the messages no longer appear.

The following fault memory entry is stored **passively** in the fault memory of the distance measuring sensor (ACC1):

- **U112300** - Data bus, received fault value (00087D)

Replacement of components in the event of this fault does not provide any remedy. Unauthorized invoiced work or unauthorized exchanged parts will be charged back.

**Information**

This TI **only applies** if the specified fault memory entry is **passively** stored in the distance measuring sensor control unit (ACC1).

If the fault memory entry is **actively** stored or another fault memory entry is stored in the distance measuring sensor control unit (ACC1), this TI is not applicable and the troubleshooting must be continued elsewhere.

- Cause: Implausible signals from the electric brake booster (eBKV) can occasionally lead to the above fault memory entry in conjunction with white messages in the instrument cluster.
- Action: If there is a customer complaint, ensure that the most current software is installed on the distance measuring sensor control unit (ACC1).  
To do this, proceed as follows:
- If there are open workshops or recall campaigns on the vehicle in question, they must first be carried out.
  - For vehicles with integration test, correct any distance measuring sensor control unit (ACC1) software or hardware deviations.

**Information**

The ACC1 has the most current software available if there are no open campaigns and if the integration test does not detect a software or hardware discrepancy for the ACC1.

- **Then** delete the fault memory entry (**U112300**) in the distance measuring sensor control unit (ACC1) - **end of action.**

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.