

Technical Information

Service

222/22 ENU 6445

5

Complaints About the Front Door Shaft Seal: Replacing Window Guide, Electric Power Windows and Front Door Window (222/22)

Change Overview:

Revision	Date	Change
0	11/23/2022	 Original publication
1	10/29/2025	 Update to 'Required Parts' section Update to 'Labor position and PCSS encryption' section title

Model Year: As of 2020 up to 2021

Model Line: Taycan (Y1A/Y1B/Y1C)

Concerns: Front window guide

Cause: Customers complain about:

- A non-closing front door window
- Noises when closing the front door window.
- A cracked or "undulating" door shaft seal

In the workshop, damage to the front door shaft seal is detected.

Cause: Complete abrasion of the anti-friction coating on the seal and/or incorrect position of the door window in the

door during the procedure.

Action required: In the event of a customer complaint, replace the window guide, electric power windows and front left and

right door window.

6445 ENU **222/22**

Technical Information

Required parts

Parts Info:	Part No.	Designation - Point of use	Quantity
	9J1837835A	⇒ Door seal window shaft seal− Front left window guide	1 piece
	9J1837433	⇒ Window guide, pillar A – Front left window guide	1 piece
	9J1837836A	⇒ Door seal window shaft seal− Front right window guide	1 piece
	9J1837434	⇒ Window guide, pillar A – Front right window guide	1 piece
	N 10447402	⇒ Internal hexagon round oval-head screw− Front window guide, left and right	4 piece(s)
	WHT003237	⇒ Internal hexagon round-head countersunk screw− Front window guide, left and right	2 piece(s)
	PAD837461A	⇒ Power windows mechanism without motor– Front left electric power windows mechanism	1 piece
	PAD837462A	⇒ Power windows mechanism without motor– Front right electric power windows mechanism	1 piece
	Laminated safety glass (LSG)		
	9J1845019C	⇒ Door window– Front left door window	1 piece
	9J1845020C	⇒ Door window– Front right door window	1 piece
	or		
	9J0845019A	⇒ Door window— Sport Turismo— Cross Turismo— Front left door window	1 piece
	9J0845020A	⇒ Door window— Sport Turismo— Cross Turismo— Front right door window	1 piece

Technical Information

Service

222/22 ENU 6445

6

Single-layer safety glass (ESG)

9J1845019B \Rightarrow Door window 1 piece

- Front left door window

9J1845020B \Rightarrow Door window 1 piece

- Front right door window

O٢

9J0845019 \Rightarrow Door window 1 piece

Sport TurismoCross Turismo

- Front left door window

9J0845020 \Rightarrow Door window 1 piece

Sport TurismoCross Turismo

- Front right door window

Replacing window guide, electric power windows and front left and right door window

Work Procedure: 1 Replace front left and right window guide.

For work procedure, see:

- ⇒ Workshop Manual '644519 Removing and installing front window guide'
- 2 Replace front left and right electric power windows mechanism.

For work procedure, see:

- ⇒ Workshop Manual '645219 Removing and installing front electric power window mechanism'
- 3 Replacing front left and right door window.

For work procedure, see:

⇒ Workshop Manual '644019 Removing and installing front door window'

6445

Technical Information

Labor position and PCSS encryption

Labor position:

ENU **222/22**

APOS	Labor operation	I No.
64451901	Removing and installing front window guide	
64451902	Removing and installing front window guide	
64521901	Removing and installing front power window mechanism	
64521902	Removing and installing front power window mechanism	
64401901	Removing and installing front door window	
64401902	Removing and installing front door window	

PCSS encryption:

Location (FES5)	64450	Front window guide
Damage type (SA4)	3042	Door seal detached

References:

- ⇒ Workshop Manual '644519 Removing and installing front window guide'
- ⇒ Workshop Manual '645219 Removing and installing front electric power window mechanism'
- ⇒ Workshop Manual '644019 Removing and installing front door window'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

Oct 29, 2025 Page 4 of 4