

## Advanced Technical Information

**Bulletin #: 2527**

Part ID: 9984G

9

## Troubleshooting Porsche NACS DC Adapter

### Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020 up to 2026	All	N/A	N/A
Macan EV	As of 2024 up to 2026	All	N/A	N/A

### Revision History

Revision	Release Date	Changes
0	October 30, 2023	Original document

### Condition

Customer complains of public charging issues at NACS DC charging stations using their Porsche NACS DC Adapter.

### Technical Background

The Porsche NACS DC Adapter can become faulty due to physical damage or misuse.

In the event of a customer complaint of a public charging issue while using the Porsche NACS DC Adapter, the adapter should be diagnosed first in order to eliminate its possible contribution to any public charging issues.

### Service Information

Please visually inspect the adapter for damage. Any physical damage is expected to be obvious to the naked eye.



**Figure 1 - Broken Pin Tip Inside Housing**


#### Procedure:

1. Visual Inspection
  - a. Verify that the adapter is the Porsche branded, official Porsche NACS DC Adapter
  - b. Check for any cracks in the housing.
  - c. Check the CCS outlet for any broken or burnt pins or melted plastic around the pins.
  - d. Check the NACS inlet for any broken or burnt pins or melted plastic around the pins.
  - e. Check that the microswitch buttons (S2 and S1 shown in *Figure 2*) can be heard as actuating when pressed on the top and bottom of the adapter respectively.

If the adapter passes the visual inspection, please check the resistance of the pins from one side of the adapter to the other with a multimeter.

#### Notes:

- A multimeter with a measuring accuracy 1.2% must be used.
  - ▷ Fluke 179/175 true RMS multimeter or an alternative multimeter with same accuracy may be used.
  - ▷ Snap-On Enhanced Multimeter EEDM535F (minimum required tool) is also acceptable.
- Pins 4 and 5 require two resistance measurements due to their dynamic nature when the respective microswitch is pressed or not.



**Figure 2 - NACS to CCS1 Electrical**

2. Resistance Check
  - a. Set multimeter to resistance measurement setting and use pin reference numbers (*Figure 3*) to measure the resistance across each pin pairing.
  - b. Record resistance measurements on the *Porsche NACS DC Adapter Measurement Sheet*, which can be found on PPN page for this bulletin.
3. Compare the resistance measurements to the chart below (*Table 1*).



Figure 3 - Reference Pin Numbers

Pin Number	NACS Pin Description	CCS Pin Description	Test Requirements
1	NACS - HV+	CCS1 - DC+	Continuity (Resistance $\leq 0.5 \Omega$ )
2	NACS - HV-	CCS1 - DC-	Continuity (Resistance $\leq 0.5 \Omega$ )
3	NACS - PE	CCS1 - PE	Continuity (Resistance $\leq 0.5 \Omega$ )
4	NACS - CP	CCS1 - CP	First Step - Continuity (Resistance $\leq 80 \Omega$ ) Second Step - press S1 (bottom switch): CP Cutoff (Open Circuit)
5	NACS - PP	CCS1 - PP	First Step - Continuity (Resistance $\leq 100 \Omega$ ) Second Step - press S2 (top switch): PP Resistance is $330 \Omega \pm 1.5\%$

Table 1: Reference Resistance Values for each pin

- Replace any adapter that fails the visual inspection or electrical checks.
- If the adapter passes all tests, follow the usual procedures to continue diagnosis of the DC public charging complaint.

### Warranty

For warranty processing, Porsche Centers should encode the PCSS cause to 9984G – NACS DC Adapter. The serial number of the defective component must be entered in PCSS under Documentation → Serial Number, as shown in Figure 4.



**Figure 4: Porsche NACS DC Adapter Serial Number**

PCSS encryption:

Location (FES5)	9984G	DC adapter NACS
Damage type (SA4)	1611	No function

### Search Items

Taycan, J1, J1PA, J1.1, J1.2, H2, Macan, Macan EV, Public Charging, DC Charging, NACS, NACS Adapter, Adapter, Charging Adapter, Porsche DC NACS Adapter

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.