

# Technical Service Bulletin

<b>Topic</b>	EPB fault warning within the DIP - DTC's stored in address 03 - C100C01 and C1246F9
<b>Market area</b>	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2074966/3
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Sep 24, 2025

## Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0003 - Brake electronics	C100C01: Electro-mechanical parking brake button Electrical malfunction		Intermittent
0003 - Brake electronics	C1246F9: Electromechanical parking brake Button interruption		Intermittent
0003 - Brake electronics	C100C01: Electro-mechanical parking brake button Electrical malfunction		static
0003 - Brake electronics	C1246F9: Electromechanical parking brake Button interruption		static

## New customer code

Object of complaint	Complaint type	Position
chassis -> brakes, brake regulation -> electronic parking brake (EPB)	functionality -> no function	

# Vehicle data

## New Continental GT / C and New Flying Spur

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z23*	2025	E		*	*	*
Z23*	2026	E		*	*	*
Z24*	2025	E		*	*	*
Z24*	2026	E		*	*	*
Z32*	2025	E		*	*	*

Z32*	2026	E		*	*	*
------	------	---	--	---	---	---

## Documents

Document name
master.xml

## Condition

EPB fault warning within the DIP with one or both DTC's as listed below:

C100C01: Electro-mechanical parking brake button electrical error

And/or

C1246F9: Electromechanical parking brake Button interruption.

## Technical Background

Refer to the Measure section of this TPI

## Production Solution

Not applicable

## Service

1. Does the EPB switch function correctly

### Comments

2. Does the LED activate on the switch and within the DIP?

### Comments

3. Can the DTC's be cleared?

### Comments

4. Referring to the applicable Rep.Gr - Remove the switch, check and confirm the connectors are fully clipped into place.

5. If no issues with the connectors are found - Inspect the harness to the switch for any pinched or trapped wiring/incorrect routing

### Comments

4. Raise a DISS or respond via a previously opened query and feedback on the above checks, ensuring a current ODIS log is attached



The EPB switch should only be replaced if all wiring checks have been completed with no issues found and permission has been given via the open DISS query