

**Technical Service Bulletin (TSB)**  
**Flash: Radio Frequency Hub Module (RFHM) Updates**

<b>REFERENCE:</b>	<b>TSB:</b> 08-146-25 REV. A <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	November 14, 2025	<b>REVISION:</b>	08-146-25
<b>VEHICLES AFFECTED:</b>	<b>2025 (WS) Grand Wagoneer / Wagoneer</b> <b>This bulletin applies to vehicles built on or before June 10, 2025 (MDH 0610XX).</b>			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input checked="" type="checkbox"/> CH <b>NOTE: **This bulletin applies to North and South America, Enlarged Europe, Middle East &amp; Africa, India &amp; Asia Pacific and China markets.**</b>	
<b>CUSTOMER SYMPTOM:</b>	<b>Customers have experienced:</b> <ul style="list-style-type: none"> <li>● <b>**Intermittent key fob detection.</b></li> <li>● <b>Possible dead batteries in key fobs.</b></li> <li>● <b>Proximity Wake-Up (welcome feature) does not activate at times.**</b></li> <li>● <b>Uconnect app requests not functioning (none of the app functions work, lock/unlock, remote start).</b></li> </ul>				
<b>CAUSE:</b>	<b>RFHM software</b>				

**This bulletin supersedes Technical Service Bulletin (TSB) 08-146-25, date of issue May 07, 2025, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include additional Customer Symptoms, Market Note, new LOP, Claims Data Note, Repair Procedure step and Note.**

**This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-091, date of issue April 01, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

**REPAIR SUMMARY:**

This bulletin involves inspecting and possibly updating the RFHM module with the latest available software.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-12-AT	Module, Radio Frequency Hub (RFHM) - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
**18-19-12-BR	Module, Radio Frequency Hub (RFHM) - Inspect Software Number and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.**
Failure Code	RF	Required Flash - RSU	
	CC	Customer Concern	

**NOTE: \*\*For EE and MEA markets only, enter the RSU spending channel for the first 18 months from the date of issue, then apply the W24.\*\***

**The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.**

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code “RF” (Required Flash) can no longer be used on Technical Service Bulletin flashes. The “RF” failure code must be used on an RSU.
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer’s VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Is the vehicle on the RSU list?
  - YES >>> [Step 2](#).
  - NO >>> Proceed to [Step 3](#).
2. Does the RFHM have the latest software already installed?
  - YES >>> This bulletin has been completed, use Inspect LOP (18-19-12-AT) to close this active RSU.
  - NO >>> Proceed to [Step 3](#).
3. Reprogram the RFHM with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The Helpdesk can be found within the Help menu.
4. **\*\*Did the RFHM reprogram successfully?**
  - YES >>> Proceed to [Step 5](#).
  - NO >>> Normal diagnostics should be performed. Refer to the detailed procedures available in DealerCONNECT.\*\*
5. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**NOTE: \*\*For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.\*\***

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*