

REFERENCE:	TSB: 18-092-25 REV. A GROUP: 18 - Vehicle Performance	Date:	November 18, 2025	REVISION:	18-092-25
VEHICLES AFFECTED:	2024 (JL) Jeep Wrangler This bulletin applies to vehicles equipped with the 3.6L V6 24V VVT Engine UPG 1 W/ESS (Sales Code ERC) and 8-Spd Auto 850RE Trans (Sales Code DFT).	MARKET APPLICABILITY:		<input type="checkbox"/> NA	<input type="checkbox"/> IAP
				<input type="checkbox"/> SA	<input type="checkbox"/> CH
				<input checked="" type="checkbox"/> EE	
				<input checked="" type="checkbox"/> **MEA	
				**	
		NOTE: This bulletin applies to the **Middle East & Africa** and Enlarged Europe markets.			
CUSTOMER SYMPTOM:	Customers may experience the following:				
	<ul style="list-style-type: none"> • Momentary hesitation in the engine when the vehicle is shifting from 3rd to 4th gear under light load and light acceleration. This occurs primarily between 1,600 and 2,100 RPM. Feels like an engine stumble or a misfire. 				
CAUSE:	PCM Software				

This bulletin supersedes Technical Service Bulletin (TSB) 18-092-25, date of issue November 06, 2025, which should be removed from your files. All revisions are highlighted with **asterisks and include an additional market.**

REPAIR SUMMARY:

This bulletin involves reprogramming the PCM with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-06-9D	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair And Performance	0.4 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.