



GROUP	MODEL
BOD	2026MY K5 (DL3)
NUMBER	DATE
346	November 2025

TECHNICAL SERVICE BULLETIN

SERVICE ACTION: REAR SEAT CARPET FLOORMAT INSPECTION AND REPLACEMENT (SA628)

This **Dealer Stock Service Action** Technical Service Bulletin provides information to inspect the rear carpet floormats on certain 2026MY K5 (DL3) vehicles:

- Produced from SOP through July 2025, equipped with hooks on the rear floor; and
- Equipped with the incorrect **Port Installed Option Carpeted Floormats (PIO Code: CF)** where rear floormats are missing positioning grommets; and
- Dealer Stock vehicle.

Follow the procedure outlined in this publication to inspect the rear carpet floormats for the positioning grommet. If it is missing, the rear carpet floormats should be replaced. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs in Dealer stock only.



NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA628.

SERVICE ACTION: REAR SEAT CARPET FLOORMAT INSPECTION AND REPLACEMENT (SA628)

Inspection & Replacement Procedure:


1. Inspect the rear passenger carpet floormats, for missing grommets.

Note: **Both left and right side.** The VIN records will have PIO Code "CF" to indicate PIO Floormats.

- If the floormat has the grommet and is secured to the floor carpet hook (**OK**), no further action is needed.
- If the floormat does not have the grommet and the floor carpet has a hook (**NG**), then replace the rear carpet floormats with a new set that includes the attachment positioning grommet to close this action.

PN: L3F14 AU200 (Rear Floormats)

Note: Check under the floormat as the rear floor carpet should have an attachment hook.




SERVICE ACTION: REAR SEAT CARPET FLOORMAT INSPECTION AND REPLACEMENT (SA628)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
K5 (DL3)	Prior to August 2026

REQUIRED PART:

Part Name	Part Number	Figure	Qty.	Comments
Rear Floor Mats (Left and Right Side)	L3F14 AU200		1	With Attached Positioning Grommets

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	L3F14 AU000	0	(SA628) Rear Floormat/Carpet Inspection	A50500IO	0.1 M/H	N/A	0
			(SA628) Rear Floormat/Carpet Inspection + Rear Floormat Replacement	A50500RO	0.1 M/H	L3F14 AU200	1

NOTE: Claims that occur after the retail date will not be accepted, as this TSB only applies to in stock VINs.

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA628 when accessing the KDealer+ system.