

982 – Exhaust Flaps Rattling

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
718 Cayman GTS 4.0 718 Boxster GTS 4.0 718 Spyder 718 Cayman GT4 718 Cayman GT4 RS 718 Spyder RS	As of 2023 up to 2025	982160 982360 982510 982810 982850 982890	N/A	N/A

Revision History

Revision	Release Date	Changes
0	November 6, 2023	Original document

Condition

Customers complain that there is a metallic rattling sound coming from the exhaust during start-up or during activation of sport exhaust. Vehicle could be in normal mode or sport.

Technical Background

Axial play in the exhaust flap bearing may lead to a rattling noise during adjustment.
See video attached to PPN page for this ATI: <https://ppn.porsche.com/portal/docs/DOC-582173>

Service Information

Replacement of the relevant hardware may not lead to a sustainable elimination of the customer complaint.

Optimized parts are in development to increase robustness regarding rattling noises. This ATI will be updated once there is a hardware replacement available for the complaint.

PCSS encryption:

Location (FES5)	25610	Actuator for exhaust flap
Damage type (SA4)	2015	Rattles

Search Items

982, 718, Cayman, Boxster, Exhaust, Flaps, Rattle

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
