

Y1A, 971, 9YB, 9YA – Brake Noise & Long Brake Pedal

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020 up to 2024	All	N/A	N/A
Panamera	As of 2019 up to 2023	PHEV	N/A	N/A
Cayenne	As of 2020 up to 2024	PHEV	N/A	N/A

Revision History

Revision	Release Date	Changes
0	November 19, 2025	Original document

Condition

Customer complains of a long brake pedal combined with a squeaking or scraping noise from the braking system when braking with light/medium brake pressure. This happens when regenerative braking is turned off so that friction brakes are used, such as after starting a drive cycle after long-term parking.

Technical Background

Runout of the brake rotor(s) or wheel hub(s) causes pulsations in the hydraulic braking system which can be heard inside the vehicle. Outside influencing factors such as accidents or impacts may cause this condition.

Service Information

Review the vehicle's history for any signs of external influence, such as accident repairs or similar events. Inspect brake rotors and hubs for runout and correct any deviations as necessary. If component integrity is uncertain, exchanging parts from a known good vehicle may aid diagnosis. Exchange parts as necessary.

Advanced Technical Information

Bulletin #: 2530

Part ID: 4701

4

Warranty

Refer to the Porsche Warranty Manual – Rules and Regulations for Warranty and Goodwill (PCNA Warranty Manual) for information on Warranty Exclusions and further information.

Search Items

Taycan, Panamera, Cayenne, Y1A, 971, 9YA, 9YB, Brakes, Rotor, Squeak, Noise

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
