

Vehicle Intermittently Not Available Via Remote Access Services: Re-program Connect Control Unit (203/21)

Change Overview:

Release	Date	Change
0	03/25/2022	<ul style="list-style-type: none"> Original publication
1	11/26/2025	<ul style="list-style-type: none"> Expanded software version check to include '0420' or higher

Model Line: **911 Carrera (992)**

Model Year: **2021**

Concerns: **Connect control unit (external communication control unit)**

Situation: Customers complain that the vehicle cannot be accessed intermittently via the Remote Access services after switching off the ignition (access to the vehicle using a smartphone). Stopping the vehicle in an area without GPS reception (e.g. underground car park) will cause a fault.

Action: In the event of a customer complaint, read and check the software version of the Connect control unit (external communication control unit) using PIWIS Tester software version **40.600.010** (or higher).

- If the software version is '**0412**' or '**0410**', re-program the Connect control unit (external communication control unit).
- If the software version is already '**0420**' (or higher), the fault must be otherwise found and remedied.

The new software version improves closed-circuit current behavior when the Vehicle Tracking System (VTS) is active and access via the Remote Access Services (access to the vehicle using a smartphone).



Information

The total time required for control unit programming is **approx. 20 minutes**.

Required tools



Information

The new 911 (992) is equipped with either a **lithium starter battery** (M no. J2A) or an **AGM starter battery** (M No. JOV, J4K) as standard.

This depends on the following:

- Country version
- Model type
- Vehicle equipment

Lithium starter batteries must only be charged using a **suitable battery charger** that has a current and voltage-controlled charge map.

For further information about the battery chargers to be used, see ⇒ *Workshop Manual '270689 Charging battery/vehicle electrical system'*.

- Tools:
- Battery charger with a current rating of **at least 90 A** and, if required, **also with a current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 – battery charger, 90A**
 - **P900999 - PIWIS Tester 4** with PIWIS Tester test software version **40.600.010** (or higher) installed

Preparatory work



WARNING

Electrically moved side windows and rear spoiler

- **Danger of limbs being trapped or severed**
 - **Risk of damage to components**
- ⇒ **Do not reach into the danger area.**
- ⇒ **Keep third parties away from the danger area.**
- ⇒ **Do not move components or tools into the danger area.**
- ⇒ **Retract roll-up sun blinds on the rear side windows before starting programming or coding.**

NOTICE

Fault entry in the fault memory and control unit programming aborted due to undervoltage.

- **Increased current draw during diagnosis or control unit programming can cause a drop in voltage, which can result in one or more fault entries and the abnormal termination of the programming process.**
- ⇒ **Before getting started, connect a suitable battery charger with a current rating of at least 90 A to the jump-start terminals.**

NOTICE

Control unit programming will be aborted if the Wi-Fi connection is unstable.

- **An unstable Wi-Fi connection can interrupt communication between PIWIS Tester and the vehicle communication interface module (VCI). As a result, control unit programming may be aborted.**
- ⇒ **During control unit programming, always connect the PIWIS Tester to the vehicle communication module (VCI) via the USB cable.**

NOTICE

Control unit programming will be aborted if the driver's key is not recognized

- **If the driver's key is not recognized in the vehicle, programming cannot be started or will be interrupted.**
- ⇒ **Place the driver's key with the back facing down in front of the lock opening for the center console cover to guarantee a permanent radio link between the vehicle and driver's key.**

- Work Procedure: 1 Carry out general preliminary work for control unit programming as described in ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming - section on "Preliminary work"*.
- 2 Read out the software version.
- 2.1 Select '**Connect**' control unit.
- 2.2 Select the "**Extended identifications**" tab.
- 2.3 Check the software version.
- If the software version is '0412' or '0410', re-program the Connect control unit (external communication control unit) using programming code 'A3D7K'.
 - If the software version is already '0420' (or higher), the fault must be otherwise found and remedied.

Re-programming the Connect control unit (external communication control unit)

NOTICE

Use of a PIWIS Tester test software version that is older than the prescribed version

- **Measure is ineffective**
- ⇒ **Always use the prescribed version or a higher version of the PIWIS Tester test software for control unit programming and coding.**

- Work Procedure: 1 The basic procedure for programming a control unit is described in the Workshop Manual ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Programming"*.

Specific information on control unit programming in the context of this Technical Information:

Required PIWIS Tester software version:	40.600.010 (or higher)
Type of control unit programming:	Control unit programming using the 'Campaign' function in the additional menu on the PIWIS Tester by entering a programming code.
Programming code:	A3D7K
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the Connect control unit (external communication control unit) is re-programmed and then automatically re-coded . Do not interrupt programming.
Programming time (approx.):	20 minutes
Software version programmed during programming:	0420 (or higher) Following control unit programming, the software version can be read from the Connect control unit in the ⇒ 'Extended identification' menu using the PIWIS Tester.
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming - section on "Troubleshooting"</i> .
Procedure in the event of abnormal termination of control unit programming:	Repeat control unit programming by restarting programming.

Follow-up actions

Work Procedure: 1 Carry out general rework for control unit programming as described in ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Rework"*.

Labor position and PCSS encryption

For documentation and invoicing in the event of a warranty, state the work item required depending on the scope of work and the specified PCSS encryption in the warranty claim:

APOS	Labor operation	I No.
91252501	Programming control units for external communication	

PCSS encryption:

Location (FES5)	91250	Control unit for external communication
Damage type (SA4)	1613	does not function occasionally

References: ⇒ *Workshop Manual '270689 Charging battery/vehicle electrical system'*
 ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming - section on "Preliminary work"*
 ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Programming"*
 ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming - section on "Troubleshooting"*
 ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Rework"*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

©2025 Porsche Cars North America, Inc.