

Technical Information

Service

75/25 ENU 9102

9

Various White Messages Regarding Driver Assistance Systems In the Instrument Cluster/Fault Memory Entry "C12D5FA" In the Control Unit for Driver Assistance Systems - ZFAS (75/25)

Model Line: Taycan (Y1A/Y1B/Y1C)

Model Year: As of 2020

Action:

Equipment: Reversing camera system (M-No. KA2)

Oſ

Real Top View (4-camera system) (M-No. KA6)

Concerns: Control unit for driver assistance systems (ZFAS)

Cause: The customer complains about the failure of various driver assistance systems and corresponding notes (white warning message) in the instrument cluster, for example:

- Assistance Systems currently reduced
- Lane Keep Assist currently not available
- Active Lane Keeping currently not available
- Speed limit display not available
- Proactive occupant protection currently reduced
- Warn and Brake Assist reduced
- Driving light control faulty
- Emergency Stop Function currently not available

After a change in readiness for operation, all systems are available again and the warning messages no longer occur.

The following fault memory entry is stored in the fault memory of the control unit for driver assistance systems (ZFAS):

C12D5FA - Control unit for driver assistance systems, image processing processor does not react

Cause: If the fault memory entry is **passive**, there is a possibility that electromagnetic incompatibility/influences on the video line may lead to the above-mentioned complaints.

If the fault memory entry is **active**, there is a possibility that the electrical contact of the image processing processor is faulty and leading to the above-mentioned complaints.

If there is a customer complaint, check whether the fault memory entry "C12D5FA" is stored actively or passively in the control unit for driver assistance systems (ZFAS) and, depending on the result, either install a new video line or replace the control unit for driver assistance systems (ZFAS).

The fault memory entry "C12D5FA" is passively stored in the control unit for driver assistance systems (ZFAS). Install the new video line. Continue with: ⇒ Technical Information 'Preparatory work for rerouting the video line'


9102 ENU **75/25**

Technical Information

٥ſ

The fault memory entry "C12D5FA" is actively stored in the control unit for driver assistance systems (ZFAS). Replace the control unit for driver assistance systems (ZFAS). Continue with: ⇒ Technical Information 'Replacing the control unit for driver assistance systems (ZFAS) (if the C12D5FA fault memory is actively stored)'

Installation Position:



Installation position for the video line - left-hand drive

- 1 Video line
- 2 Front camera for driver assistance systems
- Control unit for driver assistance systems (ZFAS)

Required parts and material for installing a new video line (passive fault memory entry)

Parts Info:	Part No.	Designation - Location	Number
	9J1998045Q	 ⇒ Repair kit for the antenna line – Including antenna connector for the control unit for driver assistance systems 	1 piece

Technical Information	Service	$\overline{}$
	75/25 ENU 9102	7102 9

⇒ Repair kit for the antenna line– Including antenna connector for the front camera	1 piece
⇒ Connecting piece– Antenna line	1 piece
 ⇒ M10 x 28 external hexagon round-head bolt − Seat rail on body − Production date up to 07/12/2023 	8 piece
 ⇒ Internal serration screw, M10 x 28 – Seat rail on body – Production date from 07/13/2023 	8 piece
 ⇒ Internal hexagon oval-head collar screw, self-locking M6 x 30 Passenger airbag unit on dashboard 	4 piece
 ⇒ Countersunk screw with internal serration, self-locking M18 x 1.5 x 18 – Steering wheel on steering column 	1 piece
⇒ Internal hexagon oval-head collar screw M6 x 12− Holder for passenger airbag on dashboard	2 piece
⇒ Internal hexagon cheese head bolt M6 x 20– Knee airbag for driver on dashboard	2 pieces (if required)*
⇒ Hexagon collar nut M6– Knee airbag for passenger on dashboard	5 pieces (if required)*
	 Including antenna connector for the front camera ⇒ Connecting piece Antenna line ⇒ M10 x 28 external hexagon round-head bolt Seat rail on body Production date up to 07/12/2023 ⇒ Internal serration screw, M10 x 28 Seat rail on body Production date from 07/13/2023 ⇒ Internal hexagon oval-head collar screw, self-locking M6 x 30 Passenger airbag unit on dashboard ⇒ Countersunk screw with internal serration, self-locking M18 x 1.5 x 18 Steering wheel on steering column ⇒ Internal hexagon oval-head collar screw M6 x 12 Holder for passenger airbag on dashboard ⇒ Internal hexagon cheese head bolt M6 x 20 Knee airbag for driver on dashboard ⇒ Hexagon collar nut M6



Information

Material: Required material (usually already available in the Porsche Center)

^{*}Screws and nuts are required for the knee airbags depending on the equipment of the affected vehicle.

`	Service
J	

9102

ENU **75/25**

Technical Information

Part No.	Designation	Quantity
	\Rightarrow Non-woven adhesive tape, approx. 19 mm (0.75 in) wide – e.g. TESA 51616 ID	As required
	⇒ Cable tie− Commercially available	As required

Required parts for replacing the control unit for driver assistance systems (ZFAS) (active fault memory entry)

Parts Info:	Part No.	Designation - Location	Number
	PAB9071XXX*	\Rightarrow Control unit for driver assistance systems	1 piece
	or		
	PAD9071XXX*	\Rightarrow Control unit for driver assistance systems	1 piece
	9A700748300	 ⇒ M10 x 28 external hexagon round-head bolt Seat rail on body Production date up to 07/12/2023 	4 piece
	or		
	PAF011175	 ⇒ Internal serration screw, M10 x 28 – Seat rail on body – Production date from 07/13/2023 	4 piece



Information

*Find which variant of the control unit for driver assistance systems (ZFAS) is required for the respective vehicle using the vehicle identification number in the Porsche Spare Parts Catalogue (PET2).

Required tools

Tools:

- P90999 Porsche Tester 4
- Battery charger with a current rating of at least 90 A and a current and voltage-controlled charge map
 for lithium starter batteries, e.g. VAS 5908 battery charger 90 A. For further information about the
 battery chargers to be used, see the corresponding Workshop Manual. ⇒ Workshop Manual '270689
 Charge battery and vehicle electrical system'
- Torque wrench 2-10 Nm (2-8 ftlb.), e.g. V.A.G 1783 torque wrench 2-10 Nm (2-8 ftlb.)
- Torque wrench 6-50 Nm (4.5-37 ftlb.), e.g. V.A.G 1331A torque wrench 6-50 Nm (4.5-37 ftlb.)
- Torque wrench 40-200 Nm (30-148 ftlb.), e.g. V.A.G 1332A torque wrench, 40-200 Nm (30-148 ftlb.)

75/25 ENU 9102

9

Additional required tools if the video line must be rerouted:

- VAS 6720 Repair set for antenna lines
- 3438 Hooks
- 9570/1 Disassembly tool
- Plastic wedge, commercially available
- Cable pull-in aid, commercially available or welding wire with bent ends

Preparatory work for rerouting the video line



Information

In order to ensure the fault-free functioning of the new video line, the new video line must be laid along the original main wire harness. Extensive preparatory work is required to make this possible.


Work Procedure: 1

- 1 Remove the (front) inner door sill trim on the left.
 - The (rear) inner door sill trim does not need to be removed completely.
 - ⇒ Workshop Manual '68051901 Removing and installing the (front) inner door sill trim'
- 2 Remove the dashboard.
 - ⇒ Workshop Manual '701819A1 Removing and installing the dashboard'
- 3 Remove the central computer.
 - ⇒ Workshop Manual '915219A1 Removing and installing the central computer'
- 4 Remove the front roof console.
 - ⇒ Workshop Manual '708319A4 Removing and installing the front roof console'
- 5 Remove the interior rearview mirror.
 - ⇒ Workshop Manual '682719A1 Removing and installing the interior rearview mirror'
- 6 Remove the left sun visor.
 - For procedure, see: ⇒ Workshop Manual '682319A1 Removing and installing the sun visor'
- 7 Loosen the roof trim in the area of the windshield to gain access to the video line in the area of the roof. For work procedure, see: ⇒ Workshop Manual '708419A4 Removing and installing the roof trim'

9102 ENU **75/25**

- 8 Expose the front camera and release and disconnect the plug connection for the video line ⇒ Electrical plug connection for front camera video line -1-.

 The front camera does not have to be removed for this. For work procedure, see: ⇒ Workshop Manual '963819A2 Removing and installing the front camera'
 - Disconnect the previous plug connection using a side cutter, secure and insulate the electrical line at a suitable point. This is no longer needed.
- 9 Release and disconnect the previous electrical plug connection for the **white** video line on the control unit for driver assistance systems (ZFAS).



Electrical plug connection for front camera video line

- Disconnect the previous plug connection using a side cutter, secure and insulate the electrical line at a suitable point. This is no longer needed.
- For left-hand drive vehicles: ⇒ Technical Information '963819A2 Rerouting the video line between the front camera (R232) and the control unit for driver assistance systems (ZFAS) - vehicles with left-hand drive'

Rerouting the video line between the front camera (R232) and the control unit for driver assistance systems (ZFAS) - vehicles with left-hand drive



Information

The new video lines are contacted at the respective front camera control unit (R232) or control unit for driver assistance systems (ZFAS) and laid along the main wire harness.

After being laid, the video lines are cut and connected to the electrical connectors from repair kit 9J1998045M.


Work Procedure: 1 Lay the new video lines.

Fasten the new video lines to the main wire harness without chafing and tension using cable ties or non-woven adhesive tape on the outside.



Information

In order to ensure the fault-free functioning of the new video lines, the new video lines must be laid along the main wire harness. Alternative routing is not expedient.




Overview of video line routing - left-hand drive

- 1.1 Contact the **new** video line 9J1998045H ⇒ Overview of video line routing left-hand drive -1- on the front camera ⇒ Overview of video line routing left-hand drive -3- and lay it in the direction of the control unit for driver assistance systems (ZFAS) ⇒ Overview of video line routing left-hand drive -4- along the main wire harness ⇒ Overview of video line routing left-hand drive -5- up to the connection point ⇒ Overview of video line routing left-hand drive -6-.
- 1.2 Contact the **new** video line 9J1998045Q \Rightarrow Overview of video line routing left-hand drive -2- on the control unit for driver assistance systems (ZFAS) \Rightarrow Overview of video line routing left-hand drive -4- and lay it along the main wire harness \Rightarrow Overview of video line routing left-hand drive -5- up to the connection point \Rightarrow Overview of video line routing left-hand drive -6-.
- 2 Lay the video line in the roof area. \Rightarrow Routing in the roof area


Routing in the roof area

Lay the video line in the area of the A-pillar. \Rightarrow Routing in the area of the A-pillar



Routing in the area of the A-pillar

4 Lay the video line in the dashboard area. \Rightarrow Routing in the dashboard area



Routing in the dashboard area

Circle - Video line connection point area


5 Connect the video lines in the dashboard area with repair kit 9J1998045M.

Technical Information

Service

75/25 ENU 9102





Connection point for video lines on the dashboard



Information

Make sure that there is sufficient line protrusion in the area of the connection point so that the new video lines are laid without chafing and tension after attaching the electrical plug connections.

- 5.1 Cut both video lines \Rightarrow Connection point for video lines on the dashboard -1 and 2- to the required length.
 - The connection point \Rightarrow Connection point for video lines on the dashboard **-Circle** should be approx. 195 mm away from the control unit for driver assistance systems (ZFAS) \Rightarrow Connection point for video lines on the dashboard **-3**-.
 - Dispose of the cut-off ends of the line; these are no longer required.
- 5.2 Attach and crimp electrical plug connections from repair kit 9J1998045M to the line ends of the video lines.
 - ⇒ Workshop Manual '912841C8 Repairing the antenna cable'
- 5.3 Contact the electrical plug connections.

Follow-up actions after rerouting of the video line

Work Procedure: 1 Fasten the roof trim panel in the area of the windshield.
For work procedure, see: ⇒ Workshop Manual '708419A4 Removing and installing the roof trim'

9102 ENU **75/25**

Technical Information

- 2 Install the left sun visor.
 - ⇒ Workshop Manual '682319A1 Removing and installing the sun visor'
- 3 Install the interior rearview mirror.
 - ⇒ Workshop Manual '682719A1 Removing and installing the interior rearview mirror'
- 4 Install the front roof console.
 - ⇒ Workshop Manual '708319A4 Removing and installing the front roof console'
- 5 Install the central computer.
 - ⇒ Workshop Manual '915219A1 Removing and installing the central computer'
- 6 Install the dashboard.
 - ⇒ Workshop Manual '701819A1 Removing and installing the dashboard'
- 7 Install the (front) inner door sill trim on the left.
 - ⇒ Workshop Manual '68051901 Removing and installing the (front) inner door sill trim'
- 8 Connect and switch on the battery charger.
 - ⇒ Workshop Manual '270689 Charging the battery/vehicle electrical system'
- 9 Connect P90999 Porsche Tester 4, establish readiness for operation and start the diagnostic application.
- 10 Read out and delete all control unit fault memories.
- 11 End the diagnostic application, end readiness for operation and disconnect **P90999 Porsche Tester 4** from the vehicle.
- 12 Switch off and disconnect the battery charger.
 - ⇒ Workshop Manual '270689 Charging the battery/vehicle electrical system'

End of action.

It is not necessary to replace the control unit for driver assistance systems (ZFAS).

Replacing the control unit for driver assistance systems (ZFAS) (if the C12D5FA fault memory is actively stored)

Work Procedure: 1

- Remove the control unit for driver assistance systems and replace it with a **new** control unit for driver assistance systems.
 - ⇒ Workshop Manual '910219A1 Removing and installing the central control unit for assistance systems'
 - ⇒ Workshop Manual '910255A1 Replacing the central control unit for assistance systems'

Technical Information

Service

75/25 ENU 9102

9

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
91282340	Rerouting the video line	
91282341	Rerouting the video line	
91025540	Replacing the central control unit for assistance systems	

PCSS encryption:

Location (FES5)	91020	Central control unit for assistance systems
Damage type (SA4)	1613	not functioning from time to time

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

©2025 Porsche Cars North America, Inc.