

<b>REFERENCE:</b>	<b>TSB:</b> 08-404-25 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	December 13, 2025	<b>REVISION:</b>	–
<b>VEHICLES AFFECTED:</b>	<b>2026 (WS) Jeep Wagoneer/ Grand Wagoneer</b> This bulletin applies to vehicles built on or before <b>October 06, 2025 (MDH 1006XX)</b> equipped with <b>Single Speed On Demand Transfer Case (Sales Code DHR)</b> or <b>2 Speed On Demand Transfer Case (Sales Code DKA)</b> .			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH <b>NOTE:</b> This bulletin applies to the North America market.	
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience one or more of the following:</b> <ul style="list-style-type: none"> <li>• Rear axle bind during slow speed turning. Feels like the 4WD is active.</li> <li>• While moving above 5 kph (3.1 mph) transmission goes into limp mode.</li> </ul>				
<b>CAUSE:</b>	<b>DTCM Software Flash</b>				

**REPAIR SUMMARY:**

This bulletin involves flashing the DTCM to the latest software level.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-07-BA	Module, Drivetrain Control - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

**The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer’s concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C’s (customer’s concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

## SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or equivalent	-	-

## DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

1. Reprogram the DTCM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*