

# Technical Service Bulletin

<b>Topic</b>	DTC P096C00 and / or P096F00 evident within the Engine Control Module
<b>Market area</b>	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2075941/3
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Dec 10, 2025

## Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0001 - Engine electronics	P096F00: Transmission Coolant Control Valve "A" Circuit Low		Intermittent
0001 - Engine electronics	P096F00: Transmission Coolant Control Valve "A" Circuit Low		static
0001 - Engine electronics	P096C00: Transmission Coolant Control Valve "A" Circuit		static
0001 - Engine electronics	P096C00: Transmission Coolant Control Valve "A" Circuit		Intermittent

## New customer code

Object of complaint	Complaint type	Position
power, vehicle electrical system, data transfer -> power supply	appearance, surface	
engine -> cooling, lubrication	functionality	
vehicle service -> inspection, maintenance -> performing a service	service: process -> with complaint confirmation	
chassis -> steering	dimensional accuracy	

## Vehicle data

### Bentayga Series - V8 Kovomo

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V14D9	2023	E		*	*	*

4V14D9	2024	E		*	*	*
4V14D9	2025	E		*	*	*
4V14D9	2026	E		*	*	*
4V15D9	2024	E		*	*	*
4V15D9	2025	E		*	*	*
4V15D9	2026	E		*	*	*
ZV14D9	2023	E		*	*	*
ZV14D9	2024	E		*	*	*
ZV14D9	2025	E		*	*	*

## Documents

<b>Document name</b>
<a href="#">master.xml</a>

## Condition

### Customer statement

Engine warning light illuminated within the DIP

### Workshop findings

One or a combination of the following DTC's are evident within the Engine Control Module (ECM)

- P096C00 Transmission coolant valve electrical malfunction

And / or

- P096F00 Transmission coolant valve short circuit to ground

## Technical Background

In the event the issue is as described the operative should conduct the instructions within the Measure section

## Production Solution

Not applicable

## Service

1) Referring to the applicable wiring diagram - Conduct an electrical integrity check of the N509 gearbox cooling valve circuit

2) Referring to Figures 1, 2 and 3 - Conduct a visual inspection to confirm if the harness shown (CIRCLE) has any damage relating to contact with the steering shaft .



Figure1



Figure 2



Figure 3

**!** NOTICE

In the event the issue is as described the operative must conduct the remaining instructions (step 3 and 4) to completion and repair the damaged cable(s)

3) Referring to Rep.Gr 97 - Wiring harness repairs - Repair the damaged wiring using the VAS 1978B wiring repair kit

4) Secure the harness as shown in Figure 4

**!** CAUTION

Ensure the wiring harness is secured / clipped to a solid location DO NOT SECURE THE HARNESS TO ANY MOVING COMPONENTS OR COOLANT HOSES




Figure 4

## Warranty

Warranty Type	110 or 910
Damage Service Number	97 09
Damage Code	00 23

### Time to conduct the applicable wiring repair

97 09 41 51 Wiring harness repair (1 cable) 30 TU

97 09 41 52 Wiring harness repair (2 cables) 40 TU

### Diagnosis time

Labour operation code 01 50 00 00

Time As per Odis log (Must not exceed 20 TU)

## Required Parts and Tools

Refer to the ETKA parts catalogue and Elsa Pro