

L634-
A.03.25

To: After Sales Official Network
Subject: RH Kidney rework
Date: 19/12/2025
Pages: 6



Campaign code:
L634-A.03.25

Campaign name:
RH Kidney rework

Model:
Temerario

Model Year:
2026

Markets:
France, Germany, Italy, Japan, Malaysia, Norway, Portugal, Singapore, Switzerland, United Kingdom, United States

VIN Involved:
Until VIN 323 (included)


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. requires internal rework RH kiney.

Solution for the field:

Remove the flaking paint and paint it again.

Spare Parts:

OPERATION B

Part Number	Description	Q.ty
4LA010535	Label	1

OPERATION C

Part Number	Description	Q.ty
4LA010535	Label	1

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation A: 0.1 h
Operation B: 0.1 h
Operation C: 3 h

Previous bulletins superseded.

None.


Rev.01
PUBLIC

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.



Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the instructions in the system’s “Manuals” section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPERATION A:**
 - o Steps to be executed: 1
 - o Labour time: 0.1 h
- **OPERATION B:**
 - o Steps to be executed: 1
 - o Labour time: 0.1 h
- **OPERATION C:**
 - o Steps to be executed: from 1 to 16
 - o Labour time: 3 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section “Service and Recall Campaigns”:

Tools/Materials required

Code	Description.	Q.ty
n\ a	3M 6405 6 mm vinyl tape	n\ a
n\ a	3M 401E paper tape	n\ a
n\ a	Mirka P240 sand paper	n\ a
n\ a	PPG Selemix 7502 anthracite primer for plastics	n\ a
n\ a	Mirka P800 sand paper	n\ a
n\ a	Matt Black 3FZ WB 2K R4404	n\ a
n\ a	Isopropanol, ISP 1510	n\ a

We kindly ask you to source bodywork materials exclusively through authorised local distributors.

Reimbursement for consumable materials is incorporated into the designated labor time for this service campaign rework operation



NOTE:


All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.



Repair method:

OPERATION A: check vehicle

If the kidney painting rework has already been completed and the 4LA010535 label has been applied, the operation is complete.




If the label is missing but the black painting rework has been completed, perform Operation B.

If the painting rework has not been completed, perform Operation C.

OPERATION B: label application

Apply 4LA010535 label



OPERATION C: rework RH kidney

Follow the instructions given in the Workshop Manual at the following path:

1. Adjustable wing (Right)- Removal procedure
Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Adjustable wing (Right) - Removal procedure*
2. Grille for adjustable wing (Right) - Removal procedure
Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Grille*

for adjustable wing (Right) - Removal procedure

3. Right wing actuator stop - Removal procedure

Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Right wing actuator stop - Removal procedure*

After that, follow the instructions below:

4. Mask the component by following these steps:
 - a. Use 3M 6405 6 mm vinyl tape to mask the component, wrapping it around the inner edge and sealing the tape inside the slit. For the remaining part of the edge that does not have a slit, simply mask it flush with the edge. See the following figures:





- b. Use 3M 401E paper tape to seal the kidney vents from the inside. Then, using a cutter, trim off the excess tape and seal the masking by placing an additional piece of tape on the outside of the vent. See the following figures:



- c. Finish the external masking by wrapping the kidney with masking paper and sealing the ends with paper tape. The kidney, both internally and externally, should ultimately appear as shown in the following figures:






5. The next step is to remove the central label inside the kidney, which triggers delamination. If necessary, use a cutter to 'lift' the paint from that point. Next, use compressed air to remove most of the paint, as shown in the figure below. Continue this operation until the compressed air is no longer effective in removing the paint.



6. Using Mirka P240 sandpaper, sand the inside of the kidney until the last layers of paint are removed or, if this is not possible, at least the 'step' between the paint and the underlying plastic layer.
7. Clean the kidney by blowing it with compressed air and using a cloth soaked in Isopropanol ISP 1510.
8. Apply PPG Selemix 7502 anthracite primer for plastics evenly until the surface is completely covered, then bake for at least 30 minutes at 80 °C and allow to cool.
9. Activate the surface using Mirka P800 fine sandpaper.
10. Apply Black Matt 3FZ WB 2K R4404 evenly, then bake for at least 30 minutes at 80 °C and allow to cool.
11. Apply 4LA010535 label



After that, follow the instructions given in the Workshop Manual at the following path:

12. Right wing actuator stop - Installation procedure
Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Right wing actuator stop - Installation procedure*
13. Grille for adjustable wing (Right) - Installation procedure
Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Grille for*



adjustable wing (Right) - Installation procedure

14. Adjustable wing (Right) - Installation procedure

Body and Chassis > Exterior > Engine Hood and Opening System > Engine hood > *Adjustable wing (Right) - Installation procedure*

After that, follow the instructions below:

- 15. Check that the right kidney is functioning correctly (opening and closing).
- 16. Perform visual inspection of areas affected by rework.



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service