

# McLaren Artura – Starter Motor Cable Inspection

<b>Bulletin type:</b>	Service Campaign
<b>Reference number:</b>	N/A
<b>Campaign reference:</b>	SCB 16 M 006
<b>Attention:</b>	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians, Retailer Parts Managers
<b>Affected vehicles:</b>	McLaren Artura
<b>Situation:</b>	Inspection of starter motor cable position
<b>Procedure:</b>	Action affected vehicles only during a service visit. Please refer to the information outlined in this document to complete the required work
<b>Date:</b>	05 December 2025

This bulletin will cover:

- 
1. Overview
  2. Procedure
  3. Warranty Information
  4. Affected Vehicles

## 1. Overview

Through continuous product quality monitoring, McLaren Automotive has identified that in some McLaren Artura vehicles, the starter motor cable may not have been fitted as per specification.

McLaren Automotive is instructing Retailers to inspect the condition of the starter motor cable and adjust the position as needed.




Image 1: Overview of work area.

## 2. Procedure

**Care Point:** Only technicians who have completed the McLaren Artura Training are allowed to work on the vehicle.

**Care Point:** The work required for the Service Campaign is **only** to be completed during a service visit.

To carry out the required check for the Service Campaign, follow the work instruction in the McLaren Service Portal (MSP) D057122 for 'Check and Adjust Starter Motor Harness'.

## 3. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the details below.

Description	Repair Time
McLaren Artura – Starter Motor Cable Inspection – Check Only	0.10 Hours
McLaren Artura – Starter Motor Cable Inspection – Check and Adjustment Required	0.15 Hours

## 4. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.