



Service Bulletin

Bulletin No.: PIP5841G

Date: January, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: DTC P04FB Due To Possible Condensation Freezing In Crankcase Pressure Sensor Assembly

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2021-2025		All	All	2.0 LSY	All
Cadillac	CT4	2020-2025		All	All	2.0 LSY	All
Cadillac	CT5	2020-2025		All	All	2.0 LSY	All
Cadillac	CT6	2019		All	All	2.0 LSY	All
Cadillac	XT4	2019-2025		All	All	2.0 LSY	All
Cadillac	XT5	2020 - 2025		All	All	2.0 LSY	All
Cadillac	XT6	2020 - 2025		All	All	2.0 LSY	All
Chevrolet	Blazer	2020 - 2025		All	All	2.0 LSY	All
GMC	Acadia	2020 - 2023		All	All	2.0 LSY	All

Involved Region or Country	North America
Condition	DTC P04FB Failed current or history
Cause	Possible moisture or condensation freezing in Crankcase Pressure Sensor assembly

Correction

If you encounter a vehicle setting DTC P04FB in temperatures below freezing that has failed current or history complete the published SI diagnostics for the DTC.

If unable to establish a root cause. Remove the PCV/Crankcase Pressure Sensor and hose assembly and inspect for presence of frozen moisture/condensation in the Crankcase

Pressure sensor and hose assembly.

If frozen moisture is present, please allow the Crankcase pressure sensor and hose assembly to thaw out and the moisture to drain completely. Use a combination of light compressed air and a shop towel to remove any residual condensation/moisture. Do not replace the Crankcase Pressure sensor.

Note: If the ambient air temperatures have not been below freezing but moisture is still present in the Crankcase pressure sensor. Remove the moisture using a combination of light compressed air and a shop towel.

Note: If this condition returns replace the Crankcase pressure sensor using the latest parts available in EPC. Additional information is currently being reviewed for MY 2019-2022.

This PI will become a Service Bulletin once additional information becomes available.

Once completed clear any remaining DTC's using GDS and evaluate.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*4088908	PCV/Crankcase Pressure Sensor and Hose Assembly Clean and Drain	.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	9
Modified	<p>02/23/2022 - Created on.</p> <p>05/11/2022 - Updated correction.</p> <p>01/27/2023- Updated to include 2023 Model Year.</p> <p>03/15/2023- Updated to include unique labor operation</p> <p>01/05/2024 Updated information to include 2024 Model Year.</p> <p>02/27/2025 Updated information to include 2025 Model Year</p> <p>04/16/2025 Updated Models.</p> <p>12/17/2025 Updated Models.</p> <p>01/09/2026- Added note regarding 2019-22MY vehicle repair currently being reviewed</p>

