

## 465 G63 - Parktronic Erroneous Warnings From Front Due to Brush Guard

---

Topic number	LI54.70-P-080191
Version	1
Function group	54.70 - Proximity warning system
Date	1/13/26
Validity	465 G63 with Front Brush Guard
Reason for change	

---

### Complaint

Consistently reproducible erroneous parktronic warnings from front.

### Cause

The parking sensors are detecting the front brush guard.

### Remedy

Complaint must be consistently reproducible.


**NOTE:** The parking system serves solely as an aid. Please review both the system function and system limitations as shown in the Operator's Manual. Certain environmental factors can affect system functionality such as hot exhaust gases or extreme heat, sensor interference, or other outside influences or aftermarket modifications.

If after verifying the complaint is consistently reproducible:

1. Remove the brush guard and verify the park distance sensors function as expected.
2. Reinstall brush guard and adjust so that it is as far away from the park sensors as possible. Typically only small adjustments are possible.
3. Check function.

If the concern is still consistently reproducible, please apply clear matte film to the locations as shown below at a minimum, although the clear matte film may be applied to the whole brush guard.



Attachments	
File	Description
<a href="#">465 G63 Brush Guard Matte Film Application.png</a> 	

## Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

## Symptoms

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Malfunction of displays > Front left display

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Acoustic warning malfunction > General

# XENTRY Tips

---

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Malfunction of displays > General

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Malfunction of displays > All displays simultaneous

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Malfunction of displays > Operates without obvious cause

Communication/information > Assistance and warning systems > Parking assist > PARKTRONIC > Acoustic warning malfunction > Operates without obvious cause

## Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------