



Service Bulletin

Bulletin No.: PIT5907E

Date: January, 2026

PRELIMINARY INFORMATION

Subject: Park Assist Module Setting Current Communication DTCs: U0101, U0131, U0146, U160F, U1611, U1610, U1614, U1615, U0132, U1607, And U1608

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2022 - 2026		All	All	All	All
Cadillac	Escalade ESV	2022 - 2026		All	All	All	All
Chevrolet	Silverado 1500-New (RPO J22, VIN Digit 12 = 5 or greater)	2022		All	All	All	All
Chevrolet	Silverado 1500	2023 - 2026		All	All	All	All
Chevrolet	Suburban	2022 - 2026		All	All	All	All
Chevrolet	Tahoe	2022 - 2026		All	All	All	All
GMC	Sierra 1500- New (RPO J22, VIN Digit 12 = 5 or greater)	2022		All	All	All	All
GMC	Sierra 1500	2023 - 2026		All	All	All	All
GMC	Yukon	2022 - 2026		All	All	All	All
GMC	Yukon XL	2022 - 2026		All	All	All	All

Involved Region or Country	North America
Condition	When inspecting for DTC's, some dealers may state that one or more of the following codes: U0101, U0131, U0140, U0146, U160F, U1611, U1610, U1614, U1615, U0132, U1607, And U1608 are set current in the Park Assist Module which may have nothing to do with why the vehicle was brought into the dealership.
Cause	This is due to a timing issue with the K182 Park Assist Module.

Correction

If you experience this concern, and everything on the data line looks correct and there are no park assist issues, please ignore these DTC's and continue with diagnosis of the customer complaint following diagnosis in SI.

Version	6
Modified	04/27/2022 - Created on. 01/06/2023 - Updated to add the repair procedure. 01/04/2023 - Updated to added 2023 Models. 01/11/2023 - Temporary remove the repair due to software issues with programming the 182 Park Assist module. 12/11/2024- Updated to add 2024 Models. 01/22/2026- Updated to add 2025-2026 model years

