

 Preview Solution CBR-2408-16

Air Production Modulator (APM) DTC C10129B - High/Excessive Flow - VN (4) - PR (4)

Published 8 January 2026

Valid For

Volvo Chassis - VN (4)

Mack Chassis - PR (4)

Model year - 2024 to curent

Introduction

This document provides guidance for addressing the APM DTC C10129B fault, "High/Excessive Flow" This fault was introduced by a previous APM software package and requires specific containment actions.

Symptom Description

DTC Code: C10129B

Description: "High/Excessive Flow" – APM (Air Production Modulator)

Cause: The DTC is triggered when the APM software continues to count flow metrics even after the engine is off. This occurs when certain nodes are in a "wake up mode."

Please follow Guided Diagnostics for fault above. If Guided Diagnostics gives a no fault found please follow steps below.

IMPORTANT NOTICE

THIS PROCEDURE IS ONE-TIME USE ONLY!

DO NOT use this procedure to clear future faults.

FOR FUTURE FAULTS, YOU MUST USE GUIDED DIAGNOSTICS!

DO NOT use it more than once.

Failure to comply with these instructions may result in improper diagnosis and incorrect repair actions. Always follow the standard troubleshooting process for any

future occurrences.

Corrective Action

Procedure

Note: Tech Tool needs to be at update to 2.8.351 or newer

To address the issue and reset the Air Cartridge Maintenance Interval, perform the following steps:

- 1. Idle the truck for 15-20 minutes.**
- 2. After 15-20 minutes, turn off the engine.**
Tech Tool requires engine-off as a precondition for the operation
- 3. Open (but do not initiate) TT operation 5618-07-03-02 under the Calibrate Tab.**


This operation resets the Air Cartridge Maintenance Interval, clearing the false readings caused by the software issue

- 4. Once the preconditions are met, click the *continue* button and start the truck again.**

Allow the engine to run for 1-2 minutes. The air system should be fully charged before beginning the operation

- 5. Begin TT operation 5618-07-03-02 Step 3.**

Note: Step 3 is only available if code C10129B is active.



- 6. Verify DTC Resolution.**

After completing the TT operation, verify that the DTC C10129B is no longer active.

IMPORTANT NOTICE

THIS PROCEDURE IS ONE-TIME USE ONLY!
DO NOT use this procedure to clear future faults.
FOR FUTURE FAULTS, YOU MUST USE GUIDED DIAGNOSTICS!
DO NOT use it more than once.

Failure to comply with these instructions may result in improper diagnosis and incorrect repair actions. Always follow the standard troubleshooting process for any future occurrences.

Important Note

This procedure is a **temporary containment measure** specifically for trucks impacted by the earlier APM software issue.

DO NOT apply this procedure for future occurrences of DTC C10129B. For any future occurrences:

- If further assistance is needed, submit an **eService case** for technical support.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article