

**WSS6 – Re-Programming 12 V Battery Sensor (Workshop Campaign)**

Model Line: **911 (992)**

Model Year: **As of 2020 up to 2026**

Concerns: **Battery sensor control unit**

Cause: **Due to a software error of the battery sensor of the 12-volt vehicle electrical system battery, it is possible that the battery data of the affected vehicles is calculated incorrectly. Depending on the usage behavior, this can result in the vehicle not starting after being parked for a longer period.**

Action: 

- Re-program the battery sensor control unit using the **latest** Porsche Tester software release.
- Minimum requirement: Version **43.800.000**

Affected Vehicles: Only vehicles assigned to the Campaign (see also PCSS Vehicle Information).  
**Every vehicle is assigned just one campaign scope.**

**Required tools**

Tool: 

- **P90999 - P90999 - Porsche Tester 4**
- Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 battery charger 90 A**

**Re-programming 12V battery sensor (campaign scope 1 - only valid for 911(992))**

Work Procedure: 1 The basic procedure for control unit programming is described in the Workshop Manual: ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Programming"*.

**For specific information on control unit programming during this Campaign, see the table below.**

Required PIWIS Tester software release:	<b>43.800.000</b> (or higher)
Type of control unit programming:	Control unit programming using the <b>'Campaign' function in the additional menu</b> on the PIWIS Tester by entering a programming code.
Programming code:	<b>B9D9M</b>

Programming sequence:	<p>Read and follow the <b>information and instructions on the Porsche Tester</b> during the guided programming sequence.</p> <p>During the programming sequence, the <b>battery sensor</b> is <b>re-programmed</b> and then <b>automatically re-coded</b>.</p> <p><b>Do not interrupt the programming and coding process.</b></p> <p>A backup documentation process for the re-programmed software releases starts after programming and coding.</p>
Programming time (approx.):	<b>15 minutes</b>
Software release programmed during this campaign:	
<p>for vehicles equipped with the battery sensor control unit in the <b>hardware version H01, H02, H03</b></p> <p>for vehicles equipped with the battery sensor control unit in the <b>hardware version H09</b></p> <p>for vehicles equipped with the battery sensor control unit in the <b>hardware version H11</b></p>	<ul style="list-style-type: none"> <li>▪ Battery sensor control unit: <b>5220</b> (or higher)</li> <li>▪ Battery sensor control unit: <b>0196</b> (or higher)</li> <li>▪ Battery sensor control unit: <b>0220</b> (or higher)</li> </ul> <p>Following control unit programming, the software version can be read out of the ⇒ 'Extended identifications' menu from the gateway control unit using the PIWIS Tester or by viewing the ECU information under the Battery sensor control unit in the Compare diagnostic data (VAL) tool in PCSS.</p> <p>The data for software part number and software version of the programmed data record are based on the specified PIWIS Tester test software release. Please note that this may change in a later release.</p>

Procedure if error messages appear during the programming sequence:	⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Troubleshooting".
Procedure in the event of a termination in the control unit programming:	Repeat control unit programming by restarting programming.

2 Read out and delete all control unit fault memories.

2.1 In the control unit selection ('Overview menu') press **F7** to call up the Additional menu.

2.2 Select the function "Read all fault memories and delete if necessary" and press **F12** ('Next') to confirm.



### Information

If control units are found to have faults that are **not** caused by control unit programming, they must first be **located** and **corrected**. This work **cannot** be invoiced under the workshop campaign number.

3 **For vehicles as of model year 2022:** Press **F3** to start the integration test in the control unit selection.

All affected control units should now be successfully programmed or checked in the control unit overview and their status.

**There must be no composite damage! Optional control unit updates (except for 12V battery sensor) should be ignored.**



### Information

If a deviation in the integration test is still indicated despite the programming carried out, this must be repeated. If the deviation persists, contact Technical Support.

4 Enter the campaign in the warranty and maintenance logbook.

## Warranty processing

Scope 1: **Re-programming 12V battery sensor**

- valid for **911 (992)**

### Labor time:

Re-programming 12V battery sensor

Labor time: **35 TU**

Includes: Connect and disconnect the battery charger  
 Connecting and disconnecting PIWIS Tester  
 Read out and delete the fault memory

⇒ **Damage number WSS6 066 000 1**

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.