

L634-
A.01.26

To: After Sales Official Network
Subject: Rework routing RH VVT cable
Date: 16/01/2026
Pages: 6



Campaign code:
L634-A.01.26

Campaign name:
Rework routing RH VVT cable

Model:
Temerario

Model Year:
2026

Markets:
Canada, France, Germany, Italy, Japan, Monaco, Spain, United Arab Emirates, United Kingdom, United States

VIN Involved:
Until VIN TLA0635


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. requires verification and possible reworking of the engine wiring and VVT connections.

Solution for the field:

Rework of the engine wiring and VVT connections.

Spare Parts:

OPERATION D

Part number	Description	Q.ty
N90937701	CABLE TIE C4.6X193	1

OPERATION E

Part number	Description	Q.ty
N90937701	CABLE TIE C4.6X193	1

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation B: 0,1 h
Operation C: 0,08 h
Operation D: 1,15 h
Operation E: 0,18 h

Previous bulletins superseded.

None.

Rev.01

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.


Doc. no.: L/V6_M06 Rev.[07]

1/6



Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the instructions in the system’s “Manuals” section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:


- **OPERATION B:**
 - o Steps to be executed: from 1 to 5
 - o Labour time: 0,1 h
- **OPERATION C:**
 - o Steps to be executed: from 6 to 10
 - o Labour time: 0,08 h
- **OPERATION D :**
 - o Steps to be executed: from 11 to 14
 - o Labour time: 1,15 h
- **OPERATION E:**
 - o Steps to be executed: from 15 to 18
 - o Labour time: 0,18 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section “Service and Recall Campaigns”:



Tools/Materials required:

Code	Description.	Q.ty
n\A	n\A	n\A



NOTE:

All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.




Preliminary operations:


OPERATION B (Only for standard version):

Follow the instructions:

1. Open the right kidney.
2. Locate the wiring (1) (right side of the motor).



3. Push the wiring (1) upwards from the bottom towards the screw/clip (circled) on the heat shield and check whether the wiring (1) comes into contact with the screw/clip.
4. If the wiring (1) does not make contact, push the wiring (1) down again, moving it as far away as possible from the screw/clip. The check can then be considered complete.
5. Close the right kidney.
6. If the wiring (1) makes contact, perform **operation D**.





Preliminary operations:


OPERATION C (Only for lightened version):

Follow the instructions given in the Workshop Manual at the following path:

7. Racing hood - lightened version (Optional) - Removal procedure

Body and Chassis > Exterior > Engine Hood and Opening System > Engine Hood > *Racing hood - lightened version (Optional) - Removal procedure*

8. Locate the wiring (1) (right side of the motor)





9. Push the wiring (1) upwards from the bottom towards the screw/clip (circled) on the heat shield and check whether the wiring (1) comes into contact with the screw/clip.

10. If the wiring (1) does not make contact, push the wiring (1) down again, moving it as far away as possible from the screw/clip. The check can then be considered complete, follow the instructions given in the Workshop Manual at the following path:

Racing hood - lightened version (Optional) - Installation procedure

Body and Chassis > Exterior > Engine Hood and Opening System > Engine Hood > *Racing hood - lightened version (Optional) - Installation procedure*

11. If the wiring (1) makes contact, perform **operation E**.






Repair method:

OPERATION D (Only for standard version):

12. Check that the wiring (1) is not damaged due to contact with the screw/clip on the heat shield.
13. If the wiring (1) is intact and undamaged, add the cable tie (N90937701) by attaching it to the second wiring (2) of the GDI pump. After applying the cable tie, check that the wiring (1) does not touch the screw/clip.



14. If the wiring (1) has suffered any kind of damage, open a claim on the Liass portal.



Repair method:

OPERATION E (Only for lightened version):

15. Check that the wiring (1) is not damaged due to contact with the screw/clip on the heat shield.
16. If the wiring (1) is intact and undamaged, add the cable tie (N90937701) by attaching it to the second wiring (2) of the GDI pump. After applying the cable tie, check that the wiring (1) does not touch the screw/clip.



17. If the wiring (1) has suffered any kind of damage, open a claim on the Liass portal.





Follow the instructions given in the Workshop Manual at the following path:

18. Racing hood - lightened version (Optional) – Installation procedure

Body and Chassis > Exterior > Engine Hood and Opening System > Engine Hood > *Racing hood - lightened version (Optional) - Installation procedure*



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service