

High-Voltage Battery cannot be Charged / Fault Memory Entry "B200000" in the High-Voltage Charger Control Unit (111/25)

Change overview

Release	Date	Change
0	01/15/2026	First publication
1	01/22/2026	Update of MY

Vehicle Type: **Panamera 4 E-Hybrid (971)**
Panamera 4S E-Hybrid (971)
Panamera Turbo S E-Hybrid (971)

Model Year: **As of 2021 up to 2023**

Equipment: **7.2 kW on-board AC charger (I-no. KB2)**

Concerns: **High-voltage charger (on-board charger - OBC)**

Information: Customers complain that it is not possible to charge the high-voltage battery. The malfunction indicator light is also activated in the instrument cluster.

One or both of the following fault memory entries is stored in the high-voltage charger control unit fault memory:

- **B200000** - Control unit, function restriction (E11C11)

and / or

- **B200000** - Control unit, function restriction (E11C17)

Action: In the event of an existing customer complaint, re-program the high-voltage charger control unit using the Porsche Tester.



Information

The minimum programming requirement is the Porsche Tester software release: **43.800.000** (or higher)

Required tools

- Tool:
- **P90999 - Porsche Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 - battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charge battery and vehicle electrical system'*

Re-programming the high-voltage charger control unit - model year M (2021)

Work Procedure: 1 Re-program the high-voltage charger control unit.

The basic work procedure for control unit programming is described in the Workshop Manual.
⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*

Specific information on control unit programming during this action:

Required Porsche Tester software release:	43.800.000 (or higher)
Type of control unit programming:	Control unit programming using the ' Campaign ' function in the Additional menu on the Porsche Tester by entering a programming code.
Programming code:	G2S3U
Programming sequence:	<p>Read and follow the information and instructions on the Porsche Tester during the guided programming sequence.</p> <p>During the programming sequence, the control unit is re-programmed and then re-coded automatically.</p> <p>Do not interrupt the programming and coding process.</p> <p>A backup documentation process for the re-programmed software releases starts once programming and coding is complete.</p>
Programming duration:	Programming takes up to 8 minutes , depending on equipment.
Software programmed during this campaign:	<p>• High-voltage charger Software release: 1192 (or higher)</p> <p>Following control unit programming, the software release can be read out from the respective control unit using the Porsche Tester in the menu ⇒ 'Extended identifications'.</p>

Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i>
Procedure in the event of the termination of control unit programming:	Repeat control unit programming by re-entering the programming code.

- 2 Read out and delete all control unit fault memories.
- 3 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - Porsche Tester 4** from the vehicle.
- 4 Switch off and disconnect the battery charger.
⇒ *Workshop Manual '270689 Charging the vehicle electrical system battery'*

Re-programming the high-voltage charger control unit - model year N, P, R (2022, 2023)

Work Procedure: 1 Re-program the high-voltage charger control unit.

The basic work procedure for control unit programming is described in the Workshop Manual.
⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*

Specific information on control unit programming during this action:

Required Porsche Tester software release:	43.800.000 (or higher)
Type of control unit programming:	Control unit programming using the 'Automatic programming' function of the control unit: 'High-voltage charger' control unit – 'Coding/Programming' menu – 'Automatic programming' function.
Programming sequence:	Read and follow the information and instructions on the Porsche Tester during the guided programming sequence. During the programming sequence, the control unit is re-programmed and then re-coded automatically . Do not interrupt the programming and coding process.

	A backup documentation process for the re-programmed software releases starts once programming and coding is complete.
Programming duration:	Programming takes up to 6 minutes , depending on equipment.
Software programmed during this campaign:	<ul style="list-style-type: none"> ▪ High-voltage charger Software release: 1192 (or higher) Following control unit programming, the software release can be read out from the respective control unit using the Porsche Tester in the menu ⇒ 'Extended identifications'.
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i>
Procedure in the event of the termination of control unit programming:	Repeat control unit programming by re-entering the programming code.

- 2 Read out and delete all control unit fault memories.
- 3 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - Porsche Tester 4** from the vehicle.
- 4 Switch off and disconnect the battery charger.
⇒ *Workshop Manual '270689 Charging the vehicle electrical system battery'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
27972549	Re-programming the high-voltage charger	

PCSS encryption:

Location (FES5)	27970	High-voltage charger
Damage type (SA4)	1614	Function not according to specification

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

©2026 Porsche Cars North America, Inc.