



TECHNICAL SERVICE BULLETIN

Classification: EL25-012	Reference: NTB26-002	Date: January 13, 2026
-----------------------------	-------------------------	---------------------------

EFFICIENCY DISPLAYS LOWER THAN EXPECTED, BUT ACTUAL DRIVING RANGE OK

APPLIED VEHICLES: 2026 LEAF (ZE2)
APPLIED DATES: Built on or before October 13, 2025

IF YOU CONFIRM

The efficiency display in the meter appears to be lower than what would be expected for the mileage that was driven, but the vehicle's actual driving range, or distance driven, is correct for the initial state of charge,

AND

CONSULT 4 (C4) indicates that a "Part number after reprogramming" is available for the A/C auto amp.

ACTION

1. Confirm that the "Current part number" for the A/C auto amp displayed in C4 is in **Table A**.
2. If applicable, reprogram the A/C auto amp.

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire **SERVICE PROCEDURE** as it contains information that is essential to successfully completing this repair.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Hold the start button for 3 seconds without a foot on the brake pedal to turn the vehicle ON. **Not Ready mode.**

HINT: This will disable DC to DC charging, allow voltage to stabilize and the reprogram to be completed with battery charger on vehicle.

2. Using CONSULT, confirm the Current A/C auto amp part number and write it on the repair order.
 - If it matches one of the part numbers in **Table A**, continue to step 2 below.
 - If it does not match one of the part numbers in **Table A**, this bulletin does not apply. Go back to ASIST for further diagnostic and repair information.

Table A

MODEL	CURRENT A/C AUTO AMP PART NUMBER: 27769-
2026 LEAF	7TC1A, 7TC3A

⚠ WARNING **⚠ CAUTION** **NOTICE**

If you are not familiar with the CONSULT Reprogramming procedure, refer to the CONSULT Operation Manual and the Electronic Service Manual (ESM) for steps to reprogram an Electronic Control Unit (ECU). Follow all precautions in both manuals to prevent possible personal injury or death and/or damage to the ECU.

3. Reprogram the A/C auto amp.

IMPORTANT: When using CONSULT 4, follow the “Vehicle Menu” and select the **Vehicle reprogramming** option under “Tool Menu” to reprogram the **A/C auto amp**.

4. After erasing all DTCs, print a copy of the CONSULT screen showing the before and after part numbers of the control unit and attach it to the repair order.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Check the Current Part Number	(1)	RXJ3AA	ZE	32	0.3
Reprogram the A/C auto amp		RXK4AA			0.5

- (1) Reference the electronic parts catalog and use the A/C Amp Assy (27760-*****) as the Primary Failed Part (**PFP**).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 13, 2026	NTB26-002	Original bulletin published