



HYUNDAI

Technical Service Bulletin

GROUP BODY ELECTRICAL	NUMBER 26-BE-001H-1
DATE FEBRUARY 2026	MODEL(S) SEE BELOW

SUBJECT: INOPERATIVE HORN ASSEMBLY REPLACEMENT
(WARRANTY EXTENSION Z09)

This TSB supersedes 26-BE-001H to add Santa Fe (TMA) and Santa Fe Hybrid (TMA HEV) to the Applicable Vehicles, Parts Information and Warranty Information.

Description: Some vehicles may have an inoperable horn that may be caused by foreign substances causing internal parts to oxidize.

Hyundai is extending the warranty coverage for the horn replacement under this condition to 10 years or 120,000 miles from the date of original retail delivery or date of first use (whichever occurs first) and is valid for original and subsequent owners.


If a horn needs to be replaced, follow the instructions within this TSB to install the latest design.

Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.

Applicable Vehicles:

Model Year	Model	Production Dates	VIN Starting w/
2021 – 2022	Santa Fe Hybrid (TM HEV)	12/18/2020 – 09/14/2023	KM8
2022 – 2023	Santa Fe Plug-In Hybrid (TM PHEV)	05/13/2021 – 09/14/2023	
2021 – 2023	Santa Fe (TMA)	10/30/2020 – 12/29/2023	5NM
2023	Santa Fe Hybrid (TMA HEV)	10/10/2022 – 12/29/2023	

Parts Information:

Model	Part Name	Part Number	Figure	Quantity
Santa Fe Hybrid (TM HEV)	Horn Assy - Low Pitch	96611-S1600QQH		1
Santa Fe Plug-In Hybrid (TM PHEV)				
Santa Fe (TMA)	Horn Assy - High Pitch	96621-S1600QQH		1
Santa Fe Hybrid (TMA HEV)				

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Santa Fe Hybrid (TM HEV)	50D196R0	Horn Assembly Replacement (both horns)	0.6 M/H	96611-S1600	I14	ZZ3
Santa Fe Plug-In Hybrid (TM PHEV)						
Santa Fe (TMA)						
Santa Fe Hybrid (TMA HEV)						

NOTE 1: If the affected parts are within the warranty period of 10 years or 120,000 miles, then submit as a campaign claim type. Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.

NOTE 2: This TSB includes repair justification photos. Op times include VIN, Mileage, and repair justification photos as outlined in the Digital Documentation Policy.

NOTE 3: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 4: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

Service Procedure:

DIGITAL DOCUMENTATION




This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

NOTICE


Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

CAUTION

Equip gloves to prevent hand injuries.



Before



After

1. Use a plastic trim removal tool to remove trim.

Disconnect the negative (-) battery terminal (A).


NOTICE

Use a plastic trim removal tool to prevent damage.



2. Refer to the shop manual to remove the front bumper assembly (B):

- **Body (Interior and Exterior) > Front Bumper > Front Bumper Assembly > Repair procedures**



3.

DIGITAL DOCUMENTATION



Using the STUI camera function, take a photo of the original (either LH or RH) horn mounted in the horizontal position.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo.





4. Refer to the shop manual to remove both horns (C, D) by disconnecting the horn connector (E) and removing the mounting bolt:

- **Body Electrical System > Horn > Repair procedure**

Tightening Torque:

lb-ft	8.7
lb-in	104.4
N.m	11.8



NOTICE

The new horns are intentionally mounted in a vertical position as opposed to the previous horizontal position.

5. Reinstall parts in the reverse order of the removal process.
6. Test the horn to confirm proper operation.
7. This service procedure is now complete.