

167 with M177 and 48V System - Yellow "Coolant" message in IC and DTC P2B2A7A The speed of the 'Coolant pump' component part is too high. A leak or defective seal was detected stored in PTCU

---

Topic number	LI20.00-P-080222
Version	1
Function group	20.00 - General
Date	2/23/26
Validity	Model series 167 with M177LS2 48 V prior to model year 2024
Reason for change	General revision of remedy and cause. Check of installed pumps omitted

---

### Complaint

Customer states that the yellow "Coolant" message is populated in the instrument cluster.

The following DTC is found stored in the PTCU:

P2B2A7A - The speed of the 'Coolant pump' component part is too high. A leak or defective seal was detected

Notes on fault code:

The fault code concerns the right rear 15 W pump on the side of the transmission (Figure 1, position C).

The fault code concerning the speed that is too high is set because of air in the system (emergency dry run function)

**IMPORTANT:** This LI DOES NOT APPLY to model year 2024 and newer vehicles. For model year 2024 and newer vehicles pump PN's A0005009100 and A0005008900 are the correct pumps

### Cause

Air in the low-temperature coolant circuit

### Remedy

PLEASE READ ALL THE STEPS AND FOLLOW THEM IN ORDER.

#### Step 1:

With the engine cold, use Xentry to activate the two pumps at the passenger front. As they are running, remove the cap from the low temp cooling circuit reservoir and observe the coolant.

- If it overflows the reservoir, or blows out upon removal of the cap there is a restriction somewhere in the coolant lines.

# XENTRY Tips

---

- This can take the form of a physical restriction inside of one of the lines or pumps or a damaged or kinked hardline or rubber hose.
- Activate each pump in succession and listen to it using a stethoscope or by placing an ear to a screwdriver or other implement placed on the pump
- Compare the sound and feel of each pump. An improperly functioning, bled, or faulty pump will make a very distinct churning noise. The pumps should be near silent and should not vibrate or heat up.
- If you find a pump that is making more noise than the others it is most likely pulling in air from somewhere or is encountering a restriction (refer to the first point in this section)
- If nothing of note is found, proceed to step 2.

## Step 2:

Disassemble underfloor paneling and wheel well interior trim at front right to gain access to the two low temperature pumps. Take note of or photograph the part number of the pump holder, along with the production date.

## Step 3:

Check the installation position of the pumps at the front right of the low-temperature circuit (Fig. 1). Below are the correct specified part numbers at each location:

- Outer: A 000 500 5500 (Fig. 1, position A)
- Inner: A 000 500 3800 (Fig. 1; position B)
- If installation position is NOK, continue to step 4
- If installation position is OK, skip to step 7

## Step 4:

Photograph the pump part numbers at the front right so that the QR-code/DMC code and the part number are visible and legible save the pictures and label them appropriately if a TIPS case is required in the future.

## Step 5:

Replace the affected pump(s) (where the installed part number differs from the specified part number, see specified part number in step 3).

## Step 6:

Use a vacuum bleeder to fill the cooling system of the low-temperature circuit.

## Step 7:

Vent the cooling system of the low-temperature circuit using XENTRY.

- **NOTE:** The cooling system of the low-temperature circuit is vented in various stages. To start with, the pumps at front right are actuated at approx. 30%, then 50% and finally at 100%. At 100% actuation, the valve of the coolant circulating the pump at the side of the transmission is opened (Fig. 1; position C).

Please ALWAYS observe the following points during the venting procedure:

- The front right pumps always run simultaneously. These pumps must NEVER be operated separately of each other for actuation or for test purposes.
- The pump at the rear of the transmission must run permanently after being actuated. If the pump only briefly starts-up and then stops again, it is in a so-called emergency dry run mode because there is too much air in the system. Please repeat the venting routine. If the rear pump at the side of the transmission remains in the emer-

# XENTRY Tips

gency dry run mode, create a TIPS case, add the previously discovered findings to it and send it to the technical support team.

- If venting is successful, you will hear hardly any flow noise at all, if necessary, the venting routine may need to be repeated several times over. If after 3 venting attempts the system still has air in it, create a TIPS case, add the previously discovered findings to it and send it to the technical support team.


WIS-References		
Document number	Title	Note
AR20.00-P-1142MNP	Drain/pour in coolant	Drain/pour in coolant

## Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms
Power generation > Engine cooling system > Indicator lamp > Illuminates yellow
Power generation > Engine cooling system > Display message > Coolant - Serviced Required

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A0005005500			Front right outer coolant pump, low temperature circuit	1		X
A0005003800			Front right inner coolant pump, low temperature circuit	1		X

Attachments	
File	Description
<a href="#">Coolant pump locations on low temperature circuit.jpg</a> 	Figure 1

# XENTRY Tips

---

Control unit/fault code	
Control unit	Fault text
N127 - Control unit "Drivetrain" (PTCU) (CPC_NG)	P2B2A7A - The rpm of component 'Coolant pump' is too high. Leakage or a defective seal was detected.

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			20701**	Please refer to this TIPS document in the dealer text