

Rear Lid Opens/does not Close - Replacing Lid for Closing Aid Motor and Upper Part of Lid Lock (118/25)

Model Line: **Macan (XAB)**

Model Year: **As of 2024**

Concerns: **Lid for closing aid motor**

Cause: **The customer complains that the rear lid cannot be opened or closed.**
 A loose microswitch in the lid for the closing aid motor can cause a faulty signal for the lid position. As a result of this, the rear lid cannot be opened, closed or locked and the message "Doors open" is displayed on the instrument cluster.

Action: If there is a customer complaint, replace the lid for the closing aid motor **and** upper part of the rear lid lock.

Required parts

Parts Info:	Part No.	Designation - Location	Quantity
	95C827888C	⇒ Rear lid for closing aid motor - Rear lid	1 piece
	95C827447A	⇒ Lid lock - Rear lid	1 piece
	PAF912032	⇒ M8 x 22 countersunk screw with internal serration - Upper part of lid lock	2 piece(s)

Required tools

- Tools:
- Torque wrench, 6-50 Nm (4.5-37 ftlb.), e.g., **V.A.G 1331A - torque wrench, 6-50 Nm (4.5-37 ftlb.)**
 - **VAS 895 015 - Disassembly wedges**

Replacing lid for closing aid motor and upper part of rear lid lock

Work Procedure: 1 Replace lid for closing aid motor and upper part of lid lock.
 For procedure, see: ⇒ *Workshop Manual '557419 Removing and installing lid for closing aid motor'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
55745540	Replace lid for closing aid motor	

PCSS encryption:

Location (FES5)	5574H	Lid for closing aid motor
Damage type (SA4)	1611	not functioning

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.