

**WSV1 – Re-Programming Gateway Control Unit (Battery Sensor) (Workshop Campaign)**

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: **As of 2025 up to 2026**

Model Line: **911 (992)**

Concerns: **Gateway control unit (battery sensor)**

Cause: **An incorrect service life limit was programmed on the affected 12-Volt vehicle electrical system battery.** This can lead to an early switch-off of the comfort consumers and to an unwarranted message "Battery low – Service necessary" in the instrument cluster.

Action: Re-program the Gateway control unit (battery sensor) using the Porsche Tester.



**Information**

The minimum programming requirement is the Porsche Tester software release: **43.800.024** (or higher).

Affected Vehicles: Only vehicles assigned to the campaign (also see PCSS Vehicle Information).

**Required tools**

- Tools:
- **P90999 - Porsche Tester 4**
  - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g., **VAS 5908 battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

**Re-program gateway control unit (battery sensor)**

Work Procedure: 1 Re-program gateway control unit (battery sensor).

The basic work procedure for control unit programming is described in the Workshop Manual.  
 ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*

**Specific information on control unit programming during this action:**

Required Porsche Tester software release:	<b>43.800.024</b> (or higher)
Type of control unit programming:	Control unit programming using the ' <b>Automatic programming</b> ' function of the control unit:  "Gateway" control unit – " <b>Coding / Programming</b> " menu – " <b>Automatic programming</b> " function.
Programming sequence:	Read and follow the <b>information and instructions on the PIWIS Tester</b> during the guided programming sequence. During the programming sequence, the <b>battery sensor</b> is <b>re-programmed</b> and then <b>automatically re-coded</b> .  <b>Do not interrupt the programming and coding process.</b>  Backup documentation for the re-programmed software releases starts after programming.
Programming duration:	Programming takes up to <b>45 minutes</b> , depending on equipment.
Software programmed during this action:	• <b>Gateway control unit (battery sensor):</b> Software release: <b>1044</b> (or higher)  Following control unit programming, the software release currently cannot be read out from the Tester. The software level can only be verified in the Post-VAL.
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i>
Procedure in the event of abnormal termination of control unit programming:	Repeat control unit programming by restarting programming.

- 2 Read out and delete all control unit fault memories.

**Information**

If control units are found to have faults that are **not** caused by control unit programming, they must first be **located** and **corrected**. This work **cannot** be invoiced under the workshop campaign number.

- 3 Press **(F3)** to start the integration test in the control unit selection.  
If there is an integration deviation for individual control units, these must be programmed before vehicle handover to the customer.



**Information**

If, despite the programming performed, a deviation is still displayed during the integration test, the test must be carried out again.

There must be no breaches of integration!

Control units with optional software can be ignored – with the exception of the Gateway control unit.

- 4 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - Porsche Tester 4** from the vehicle.
- 5 Switch off and disconnect the battery charger.  
⇒ *Workshop Manual '270689 Charging the vehicle electrical system battery'*
- 6 Enter the campaign in the Warranty and Maintenance logbook.

**Warranty processing**



**Information**

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary work and rework. The labor time can differ from the labor time published in the Labor Operation List in the PCSS.

Scope 1:

**Re-program gateway control unit (battery sensor)**

**Labor time:**

Re-program gateway control unit (battery sensor)

Labor time: **74 TU**

- Includes:
- Connecting and disconnecting battery charger
  - Connecting and disconnecting PIWIS Tester
  - Read out and delete fault memories

⇒ **Damage code WSV1 066 000 1**

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.