

WPD8 Workshop Campaign – Re-Programming High-Voltage Battery Control Unit (BMC)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: **As of 2017 up to 2024**

Change Overview:

Revision	Date	Change
0	04/09/2025	<ul style="list-style-type: none"> ▪ First Publication
1	05/29/2025	<ul style="list-style-type: none"> ▪ Update of PIWIS Tester release version ▪ Addition of Information regarding the SOC (State of Charge)
2	02/26/2026	<ul style="list-style-type: none"> ▪ Addition of Step 2 in work procedure ▪ Addition of scope 2 ▪ Update of PIWIS Tester release version

Model Line: **Cayenne (9YA/9YB), Panamera (971)**

Concerns: **High-voltage battery control unit (BMC)**

Cause: **Due to a software error in the high-voltage battery control unit (BMC), the calculation of the calibration test number (CVN) cannot be carried out in full on the affected vehicles.**

This may lead to incomplete output of the on-board diagnostics in the event of a fault in the high-voltage battery (BMC) control unit. As a result, country-specific regulations are not fulfilled.

Action: Re-program the high-voltage battery control unit (BMC), and depending on the vehicle condition individual cell modules, with the **latest** PIWIS Tester software release.

Minimum requirement: Release **43.800.040**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Required tools

- Tools:
- **P90999 - PIWIS Tester 4**
 - Battery charger with a current rating of **at least 90 A**, e.g. **battery charger 90A**

Re-program high-voltage battery control unit (BMC)

- Work Procedure: 1 The basic procedure for programming a control unit is described in the Workshop Manual ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester – section on "Programming"*.

**Information**

Please note, that the SOC (State of Charge) of the battery must not be below 40% before starting the re-programming.

- 2 Select **Additional menu** in the control unit overview and start '**Check battery capacity for campaign WPD8**' by pressing **(F12)** .

Assessment	Action
Calculated value below 80%	After successful programming, the SOH must be re-taught. Perform ⇒ .
Value determined above 80%	No further action is necessary after successful programming. Perform ⇒ .

- 3 **For specific information on control unit programming during this Campaign, see the table below.**

Required PIWIS Tester software release:	43.800.040 (or higher)
Type of control unit programming:	Control unit programming using the " Automatic programming " function of the gateway control unit: "High-voltage battery" control unit – " Coding/Programming " menu – " Automatic programming " function.

Programming sequence:	<p>Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence.</p> <p>Do not interrupt the programming and coding process.</p> <p>A backup documentation process for the re-programmed software releases starts as soon as programming and coding is complete.</p>
Programming time (approx.):	50 minutes
Software release programmed during this campaign for vehicles depending on vehicle condition:	<p>Panamera (971)</p> <ul style="list-style-type: none"> ▪ High-voltage battery control unit (37 Ah) : 0293 ▪ High-voltage battery control unit (48 Ah) : 0373 or 0371 <p>Cayenne (9YA/9YB)</p> <ul style="list-style-type: none"> ▪ High-voltage battery control unit (37 Ah) : 0293 ▪ High-voltage battery control unit (48 Ah) : 0373 or 0371 <p>Following control unit programming, the software release can be read out from the relevant control unit using the PIWIS Tester in the menu ⇒ "Extended identifications".</p>
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Troubleshooting"</i> .
Procedure in the event of a termination in the control unit programming:	Repeat control unit programming by restarting programming.

- 4 Read out all **fault memories**, process and delete existing faults if necessary.



Information

If control units are found to have faults that are **not** caused by control unit programming, these must first be **found and corrected**. This work **cannot** be invoiced under the workshop campaign number.

**Information**

Step 5 is only required if the value determined in Step 2 is **below 80%**.

- 5 Select '**high-voltage battery**' control unit and open the '**Maintenance/repairs**' menu. Start the '**State of health**' function by pressing **(F12)** and follow the instructions for the procedure.
- 6 Enter the campaign in the Warranty and Maintenance Logbook.
Continue to warranty processing ⇒ *Technical Information '9X00IN Warranty processing'*

Warranty processing

Scope 1: **Re-program high-voltage battery control unit (BMC)**

Labor time:

Re-program high-voltage battery control unit (BMC)

Labor time: **76 TU**

Includes: Connect and disconnect the battery charger
Connecting and disconnecting PIWIS Tester
Read out and delete the fault memory

⇒ **Damage number WPD8 066 000 1**

Scope 2: **Re-program high-voltage battery control unit (BMC) and re-teach SOH of the high-voltage battery**

Labor time:

Re-program high-voltage battery control unit (BMC)

Labor time: **149 TU**

Includes: Connect and disconnect the battery charger
Connecting and disconnecting PIWIS Tester
Re-teach SOH
Read out and delete the fault memory

Additional costs:

WPD80000001* Power consumption Quantity as required
(for warranty invoicing only)

*For warranty processing, the **part number WPD800000001** with the designation "Energy Consumption" can be invoiced as an **additional part** in the warranty claim. Maximum amount €10.

⇒ **Damage number WPD8 066 000 1**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.