

SF735 A

February 2026

**Adaptive Cruise Control (ACC): Cummins Medium Duty Engines**

Models Affected				
Make	Model	Model Year	Prod. Start Date	Prod. End Date
Freightliner	108SD	2026	01/21/2025	05/19/2025
	114SD	2026	01/22/2025	02/20/2025
	M2106	2026	01/13/2025	06/06/2025
	M2112	2026	01/16/2025	05/30/2025
Western Star	47X	2026	04/25/2025	04/25/2025
Identifying Feature	Vehicles equipped w/ B6.7 or L9 Cummins engines and a specific software package.			

**General Information**

On behalf of the entities listed below, Daimler Truck North America LLC (DTNA) is initiating Field Service Campaign SF735 to modify the affected vehicles.

- Freightliner Trucks Division
- Western Star Truck Sales, Inc.

**PROBLEM:** Due to a software integration delay, certain vehicles ordered with Detroit Assurance were not equipped with Adaptive Cruise Control (ACC).

**SOLUTION:** Parameters will be updated to enable ACC.

There are approximately 4,861 vehicles involved.

**Additional Repairs**

Dealers must complete all outstanding Recall and Field Service campaigns prior to the sale or delivery of a vehicle. A Dealer will be liable for any progressive damage that results from its failure to complete campaigns before sale or delivery of a vehicle.

Owners may be liable for any progressive damage that results from failure to complete campaigns within a reasonable time after receiving notification.

Please contact Warranty Campaigns for consideration of additional charges prior to performing the repair.

**Work Instructions**

Please refer to the attached work instructions. Prior to performing the campaign, check the vehicle for a completion sticker (Form WAR261).

**Replacement Parts**

If our records show your dealership has ordered any vehicle(s) involved in campaign number SF735, a list of the customers and vehicle identification numbers will be available on the DTNA Portal via OWL.

**NOTE:** No parts are required for this repair.

SF735 A

February 2026

**IMPORTANT - After Repair is Complete:**

Write the campaign number on a red completion sticker (WAR261) and attach sticker to the base label (WAR259).

If the vehicle does not have a base label, clean a spot on the appropriate location and attach a base label prior to attaching the completion sticker.

Failure to install a completion sticker may result in a chargeback of the campaign claim.

**Table 1 – Completion Sticker**

Group	Sticker Number	Description	Qty
A	WAR261	Blank Completion Sticker	1

**Removed Parts**

- For U.S. and Canadian Dealers, use the part disposition to determine how to manage removed parts (return, scrap, etc.). Dispositions are available at the date of the repair.
- For Export Dealers, destroy removed parts unless otherwise advised.

**Claim Reimbursement - Labor Allowance**

**IMPORTANT:** OWL must be viewed prior to performing the Field Service campaign to ensure the vehicle is involved and the campaign has not been previously completed. Also check for a completion sticker prior to beginning work.

You will be reimbursed for your parts, labor, and handling (landed cost for Export Distributors) by submitting your claim through the warranty system within 30 days of completing this campaign.

- In OWL, use the 'Retrieve' function and select the appropriate procedure. This will auto-populate the PFP, component code, cause, corrective action, and SRT code.

**Table 2 - Claim Reimbursement**

<b>Claim Type</b>	Field Service Campaign
<b>Campaign</b>	SF735 A
<b>VMRS Component Code</b>	F99-999-005
<b>Cause Code</b>	A1 – Campaign
<b>Primary Failed Part</b>	25-SF735-000

**Table 3 – Labor Allowance**

Group	Procedure	Time Allowed (hours)	SRT Code	Corrective Action
A	Update Parameters	0.3	996-F251A	12-Repair Recall/Campaign

**SF735 A**

**February 2026**

## **Claims for Credit**

- Claim type is Field Service Campaign.
- In the Campaign field, enter the campaign number and group (SF735-A).
- In the Primary Failed Part field, enter 25-SF735-000.
- In the Parts section, no entry is required as this is a software update.
- In the Labor section, enter the appropriate SRT from the Labor Allowance Table. Administrative time will auto-populate if applicable using SRT 939-6010A for 0.3 hours (0.4 hours for RVs).
- The VMRS Component Code is F99-999-005 and the Cause Code is A1 - Campaign.
- U.S. and Canada – Reimbursement for Prior Repairs. When a customer asks about reimbursement, please do the following:
  - Accept the documentation of the previous repair.
  - Make a brief check of the customer's paperwork to see if the repair may be eligible for reimbursement. (See the 'Copy of Owner Letter' section of this bulletin for reimbursement guidelines.)
  - Submit an OWL Field Service Pre-Approval Request for a decision.
  - Include the approved amount on your OWL claim in the Other Charges section.
  - Attach the documentation to the pre-approval request.
  - If approved, submit a 'based on claim' for the pre-approval.
  - The Dealer is required to reimburse the customer the appropriate amount.

**IMPORTANT:** OWL must be viewed prior to performing the Field Service campaign to ensure the vehicle is involved and the campaign has not been previously completed. Also check for a completion sticker prior to beginning work.

U.S. and Canadian dealers, if you have any questions, contact the Warranty Campaigns Department by submitting an inquiry through the Prism Network Assist (PNA) at [DTNAPortal.com/PNA](http://DTNAPortal.com/PNA). Export distributors, submit a ticket via the Prism Network Assist (PNA) at [DTNAPortal.com/PNA](http://DTNAPortal.com/PNA), or contact your International Service Manager.

U.S. and Canadian Dealers: To return excess kit inventory related to this campaign, U.S. dealers must submit a Parts Authorization Return (PAR) to the Memphis PDC. Canadian dealers must submit a PAR to their facing PDC. All kits must be in resalable condition. PAR requests must include the original purchase invoice number. Export Distributors: Excess inventory is not returnable.

The letter notifying U.S. and Canadian vehicle owners is included for your reference.

Please note that the National Traffic and Motor Vehicle Safety Act, as amended (Title 49, United States Code, Chapter 301), requires the owner's vehicle(s) be corrected within a reasonable time after parts are available to you. The Act states that failure to repair a vehicle within 60 days after tender for repair shall be prima facie evidence of an unreasonable time. However, circumstances of a particular situation may reduce the 60-day period. Failure to repair a vehicle within a reasonable time can result in either the obligation to (a) replace the vehicle with an identical or reasonably equivalent vehicle, without charge, or (b) refund the purchase price in full, less a reasonable allowance for depreciation. The Act further prohibits dealers from selling a vehicle unless all outstanding recalls are performed. Any lessor is required to send a copy of the recall notification to the lessee within 10 days. Any subsequent stage manufacturer is required to forward this notice to its distributors and retail outlets within five working days.

**SF735 A**

**February 2026**

## **Copy of Notice to Owners**

### **Adaptive Cruise Control (ACC): Cummins Medium Duty Engines**

Daimler Truck North America LLC (DTNA), on behalf of its Freightliner Trucks Division, and wholly owned subsidiary, Western Star Truck Sales, Inc. is initiating Field Service Campaign SF735 to modify specific model year 2026 Freightliner 108SD, 114SD, M2, and Western Star 47X vehicles, manufactured January 13, 2025 to June 6, 2025.

Due to a software integration delay, certain vehicles ordered with Detroit Assurance were not equipped with Automatic Cruise Control (ACC).

Parameters will be updated to enable ACC.

Please contact an authorized DTNA dealer to arrange to have the campaign performed. The campaign will take approximately one hour and will be performed **free of charge**. To locate an authorized dealer go to <https://northamerica.daimlertruck.com/brands/support>. At the bottom of the page click on the appropriate brand (shown as an icon), and at the top of each brand's page is an option to 'Find a Dealer'.

This Field Service Campaign will **terminate on February 28, 2027**. Please make sure the campaign is completed prior to this date. Work completed after this date will be done at the customer's expense.

As stated in the terms of your express limited warranty, Daimler Truck North America LLC will not pay for any damage caused by failure to properly maintain your vehicle. Daimler Truck North America LLC considers the work necessary under this campaign to be proper maintenance and, therefore, will not pay for any damage to your vehicle caused by your failure to have the repairs that are the subject of this campaign performed in a reasonable time.

If you have any questions, contact the Warranty Campaigns Department at (800) 547-0712, from 7 a.m. to 4 p.m. Pacific Time, Monday through Friday, e-mail address: [dtna-war-campaigns@daimlertruck.com](mailto:dtna-war-campaigns@daimlertruck.com), or contact the Customer Assistance Center at (800) 385-4357.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

SF735  
February 2026

## Work Instructions

### Adaptive Cruise Control (ACC): Cummins Medium Duty Engines

Models Affected				
Make	Model	Model Year	Prod. Start Date	Prod. End Date
Freightliner	108SD	2026	01/21/2025	05/19/2025
	114SD	2026	01/22/2025	02/20/2025
	M2106	2026	01/13/2025	06/06/2025
	M2112	2026	01/16/2025	05/30/2025
Western Star	47X	2026	04/25/2025	04/25/2025
Identifying Feature	Vehicles equipped with B6.7 or L9 engines and a specific software package.			

## Update Parameters: Adaptive Cruise Control (ACC)


1. Check the base label (WAR259) for a completion sticker for SF735 (WAR261), indicating this work has been done. The base label is usually located on the passenger-side door, about 12 inches (30 cm) below the door latch. If a completion sticker is present, no work is needed. If a completion sticker is not present, proceed to the next step.
2. Park the vehicle on a level surface, shut down the engine, and set the parking brake. Chock the tires.
3. Connect to the Electronic Control Module (ECM) using Cummins INSITE™ or Guidanz®. Verify that the ECM is running the latest calibration. INSITE automatically checks for updates. The required software version is Rev. 19, which is the current release.
4. Set the ECM value for the 'Adaptive Cruise' parameters listed below. See [Fig. 1](#).

Features and Parameters	ECM Value
Adaptive Cruise	Enable
Adaptive Cruise Recovery	Adaptive
Adaptive Cruise Control Auto Resume	Enable
Auto Resume Lower Speed Limit	20 mph
Auto Resume Type	Auto Resume Enabled

5. For the engine brake performance to match the intended performance, confirm the ECM values for the 'Cruise Control and Engine Brake Interaction' parameters are set as listed below. See [Fig. 1](#).

Features and Parameters	ECM Value
Cruise Control and Engine Brake Interaction	Enable
Start Maximum Braking	2.0 mph
Start Minimum Braking	0.5 mph
Cruise Control Engine Brake Switch Bypass	Enable

SF735  
February 2026



Parameter	ECM Value	Units
Cruise Control	Enable	
Predictive Cruise Maximum Negative Offset	5.0	mph
Predictive Cruise Maximum Positive Offset	1.0	mph
Cruise Control Type	Predictive	
Cruise Control Lower Droop	5.0	mph
Cruise Control Upper Droop	3.0	mph
Maximum Cruise Control Speed	75	mph
<b>Adaptive Cruise</b>	<b>Enable</b>	
Adaptive Cruise Recovery	Adaptive	
<b>Adaptive Cruise Control Auto Resume</b>	<b>Enable</b>	
Auto Resume Lower Speed Limit	20	mph
Auto Resume Type	Auto Resume Enabled	
Adaptive Cruise Usage Demand	Enable	
Cruise Control Accelerator Override	Enable	
Cruise Control Auto Resume	Disable	
Cruise Control On Off Switch	Disable	
Cruise Control Pause Switch	Enable	
Cruise Control Save Set Speed	Disable	
<b>Cruise Control and Engine Brake Interaction</b>	<b>Enable</b>	
Start Maximum Engine Braking	2.0	mph
Start Minimum Engine Braking	0.5	mph
<b>Cruise Control Engine Brake Switch Bypass</b>	<b>Enable</b>	

02/19/2026 f121716

A. Set the ECM values as shown. B. Confirm the ECM values are set as shown.

Fig. 1, ECM Parameters in Cummins INSITE

6. Send the changes to the ECM, and disconnect the ECM from Cummins INSITE.
7. Turn the keyswitch to the 'Run' position.
8. Connect an RP1210B-compliant vehicle diagnostic adaptor to the diagnostic connector on the vehicle.
9. Connect the other end of the adaptor to the laptop. Ensure the laptop is connected to a power source.

SF735  
February 2026

- Open DiagnosticLink®.  
IMPORTANT: Make sure that DiagnosticLink is updated to the latest version (8.23 SP1 at the time of publication or newer) before programming the vehicle.
- Use the DTNA Portal credentials to connect DiagnosticLink to the server.
- Go to the 'Program Device' tab, and make sure that the Vehicle Identification Number (VIN) is correct. Select 'Download data from server.' See Fig. 2.




Fig. 2, Downloading Data from the Server

SF735  
February 2026

- 13. From the menu bar, select 'File,' then select 'Connect.'
- 14. In the 'Manual Connection' window that appears, verify that 'CGW04T' and 'ICUC01T' devices are connected. See Fig. 3.




Fig. 3, Manual Connection Window

SF735  
February 2026

15. Go to the 'Parameters' tab. Select and expand the 'CGW04T - Central Gateway' parameter folder.
16. Select and expand the 'GVCDData' parameter subfolder.
17. Select the 'GVC Adaptive Cruise Control Function' parameter, and set the parameter value to 'A0134475627-001 GVC ACC: Adaptive Cruise Control.' See Fig. 4.

08/11/2025


- A. Go to the 'Parameters' tab.
- B. Select and expand the 'CGW04T - Central Gateway' parameter folder.
- C. Select and expand the 'GVCDData' parameter subfolder.
- D. Select the 'GVC Adaptive Cruise Control Function' parameter.
- E. Set the parameter value to 'A0134475627-001 GVC ACC: Adaptive Cruise Control.'

Fig. 4, Setting the Adaptive Cruise Control Function Parameter Value



**SF735  
February 2026**

19. Select and expand the 'ICUC01T - Instrument Cluster' parameter folder.
20. Select and expand the 'PID 0x45 (FTL config)' parameter subfolder.
21. Select the 'paramCCBackUp' parameter, and set the parameter value to 'A0444472921-001 paramCCBackUp paramCCBackUp not available.' See [Fig. 6](#).



08/11/2025

f121714

- A. Select and expand the 'ICUC01T - Instrument Cluster' parameter folder.
- B. Select and expand the 'PID 0x45 (FTL config)' parameter subfolder.
- C. Select the 'paramCCBackUp' parameter.
- D. Set the parameter value to 'A0444472921-001 paramCCBackUp paramCCBackUp not available.'

**Fig. 6, Setting the paramCCBackUp Parameter Value**

SF735  
February 2026

22. Select and expand the 'PID 0x43 (FTL config)' parameter subfolder, and select the 'paramDASMenuHysteresis' parameter. Set the parameter value as listed below. See Fig. 7.

Vehicles Equipped with ..	Parameter Value
Fixed Headway Control	A0414470021-001 paramDASMenuHysteresis not available
Adjustable Headway Control	A0414470121-001 paramDASMenuHysteresis available

08/11/2025 f121715

- Select and expand the 'PID 0x43 (FTL config)' parameter subfolder.
- Select the 'paramDASMenuHysteresis' parameter.
- For vehicles equipped with fixed headway control, set the parameter value to 'A0414470021-001 paramDASMenuHysteresis not available.'
- For vehicles equipped with adjustable headway control, set the parameter value to 'A0414470121-001 paramDASMenuHysteresis available.'

Fig. 7, Setting the paramDASMenuHysteresis Parameter Value

SF735  
February 2026

23. Select the 'Send' button to write the parameter changes to the CGW04T and ICUC01T ECUs in the vehicle. A window opens asking to confirm the parameter changes; select 'OK.' See Fig. 8.





Fig. 8, Writing the Parameter Changes to the Vehicle

SF735  
February 2026

24. Once the parameter change is complete, go to the 'Program Device' tab, then select 'Unit data management' in the upper-right corner. See **Fig. 9**.



**Fig. 9, Selecting Unit Data Management**

SF735  
February 2026

25. The information corresponding to the VIN should appear under 'Unit data for upload.' Select 'Connect to server' to upload the new parameters. See Fig. 10.




Fig. 10, Uploading the New Parameters

26. Once the parameter updates are uploaded to the server, disconnect the vehicle from DiagnosticLink.
27. Turn the keyswitch to the OFF position.
28. Clean a spot on the base label (Form WAR259) and attach a campaign completion sticker for SF735 (Form WAR261).