

Technical Service Bulletin (TSB)
Battery Drain - Restore Vehicle Configuration

REFERENCE:	TSB: 08-050-26 REV. A GROUP: 08 - Electrical	Date:	February 17, 2026	REVISION:	08-050-26
VEHICLES AFFECTED:	2026 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles built on or before February 03, 2026 (MDH 0203XX) equipped with 2.0L Hurricane 4 Turbo Turbo w/ESS (Sales Code EC7) and Passive Entry-FRT Doors, Liftgate (Sales Code GXD).		MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> CH NOTE: This bulletin applies to the North American market.		
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> • Keyless Ignition Node (KIN) stays illuminated after vehicle ignition is OFF. • Depleted battery. NOTE: Battery depleted due to a 100mA ignition-off draw.				
CAUSE:	**Ignition-off draw**				

This bulletin supersedes Technical Service Bulletin (TSB) 08-050-26, date of issue February 07, 2026, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include updated Cause, Repair Summary, LOP description, Repair Procedure step and note.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-028, date of issue February 07, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

****This bulletin involves performing a Restore Vehicle Configuration routine.****

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-02-JN	Perform **Restore Vehicle Configuration and** PROXI Configuration Alignment (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZY	Service Action	

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

1. ****Using the wiTECH, perform the "Restore Vehicle Configuration" routine. This routine is available under the 'Guided Diagnostics' tab of the wiTECH.****

NOTE: **The "Restore Vehicle Configuration" routine will cause two DTCs to set:

- **B259C-13 - Rear Left Door Handle Sense-Circuit Open.**
- **B259D-13 - Rear Right Door Handle Sense-Circuit Open.**

This is a known and expected configuration issue. Do NOT replace the Radio Frequency Hub Module (RFHM) or the rear door handles. There is no functional impact to the customer and no hardware components are faulty.**

2. After completing the "Restore Vehicle Configuration: routine, perform a :PROXI Configuration Alignment: routine.

NOTE: PROXI Configuration Alignment must be run to finish updating the vehicle configuration.

3. Clear any DTCs that may have set (except the two DTCs listed above).

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.